

United Parks & Parkways Thematic Resources:

1 Side Subdivision (East) Historic District, Buffalo, Erie County, NY

Item 3 Page 137

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Main Street, northwest side only</u>			
2130	c.1909		Two and one-half story, frame Colonial Revival style residence with flat top hip roof with flared eaves, paired ancone brackets under eaves; partial width hip roof porch, fluted Doric columns support entablature, spindle balustrade, opaque glass paneled door; first story end bays have two-story semi-hexagonal bays with double-hung windows; pedimented gable dormer with paired corner brackets under cornice, three double-hung windows; east side entrance has glass and wood paneled door flanked by paneled pilaster strips supporting entablature, dentils under cornice, semi-hexagonal hip roof bays flank entrance; second story center bay has semi-hexagonal oriel, double-hung windows in bays and flanking oriel. Contributing one-story garage.
2136	c.1929	98	Two-story, brick Italian Renaissance style residence hall with simple hip roof with boxed overhanging eaves; flat symmetrical front facade, center bay has two-story blind arcade in stone, Doric pilaster strips, glass and wood paneled door flanked on one side by eight-light sidelights, Doric pilaster strips flank and support semi-circular moulded arch, key-stone with moulded stone curves enfaming medallion; second story has double-hung window, semi-circular stone arch above decorated with highly carved laurel, square panel in stone etched with '2136'; first and second story end bays have tripartite double-hung windows, paneled apron, wrought-iron balcony and relieving arch.
2142	c.1924	98	Two and one-half story, brick Colonial Revival style residence with side gable roof with cornice end returns; basement level windows, rectangular three-light with entablature window head; first story end bays have double-hung windows, blind semi-circular arch with fan motif decorating, relieving arch with stone keystone and end stops, apron with false wrought-iron balcony; second story has double sash, double-hung windows, paneled shutters; frieze at roof line decorated with triglyphs and bull's-eye motifs; south side has pedimented main entrance with cornice end returns, lighted door flanked by pilaster strips, filled-in fan light decorated with fan motif, sidelights, relieving arch with keystone. Contributing one-story brick garage.
2148	c.1897	98	Two and one-half story, frame Queen Anne style residence with front facing gable roof; full-width flat roof porch with extending eaves, ancone brackets under entrance eave, stucco base, end pilasters, single double-hung window flanks recessed entrance, wood paneled door; second story

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Main Street, northwest side only</u>			
2148(cont'd)			semi-hexagonal bay, center single light window with double-hung windows on sides; two-story tower extends from second story, conical bell-cast roof, decorative shingles; second story has double-hung windows; third story single light windows, entablature window surrounds; pedimented gable, shingled has modillion blocks and end bracket under projection, pair of single light windows; pedimented gable dormers on side. Contributing; one-story hip roof garage.
2152	c.1914		Two-story, frame "American Four Square" residence with hip roof with exposed rafter-tails under projecting eaves; hip roof dormer with exposed rafter-tails under projecting eaves, three six-light windows with entablature surrounds; one-story semi-circular facadewing has flat roof with exposed rafter-tails under projecting eaves, brick base, engaged Doric columns flank window bays, each bay has two single-light windows flanked by sidelights and leaded transom, paneled apron; second story wood paneled porch door flanked by double-hung windows, entablature window and door surrounds; south side has flat roof entrance hood supported by single curved brackets, glass paneled door with horizontal and vertical glass bands enframing panel. Contributing one-story hip roof garage.
2156	c.1910		Two and one-half story, frame residence with front facing gable with cornice end returns; full-width hip roof enclosed wing and entrance porch, Doric columns flank porch entrance and support entablature that spans entire wing, dentils under cornice, paneled wood door with sidelights; enclosed portion of first story has three double-hung windows; second story shed roof boxed bay spans entire story, right end bay has two double-hung windows, left end bay three double-hung windows; gable has two one/one sash-type windows; south side one-story enclosed entrance porch, hip roof, six panel wood door; two-story semi-hexagonal bay with projecting cross gable. Asbestos siding. Contributing one-story garage.
2162	c.1911		Two-story, brick and stucco "American Four Square" residence with hip roof with projecting eaves; hip roof dormer with projecting eaves and three double-hung windows; full-width hip roof one-story enclosed porch, brick first story, band course at second story level; south side has semi-circular entrance porch, Doric columns support entablature, dentils under cornice, wrought-iron balustrade for balcony, wood paneled door flanked by decorative iron sconces; second story front facade has two double-hung windows and stucco.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Main Street, northwest side only</u>			
2166	c.1909		Two-story, frame "American Four Square" residence with hip roof with projecting eaves; hip roof dormer with flared eaves, modillions under eaves, single double-hung window; full-width flat roof enclosed porch with extending eaves, brick base and piers, glass and wood door, double-hung window flanks door on one side, four one/one windows to left of entrance, brick piers flank window bays; second story has two semi-hexagonal bays, capping cornice, double-hung windows. Asbestos siding.
2170	c.1910		Two-story, brick "American Four Square" residence with hip roof with curved brackets under projecting eaves; hip roof dormer with projecting eaves, two double-hung windows flanked by fluted pilaster strips; full-width hip roof porch, enclosed, has pediment over entrance, ancone brackets under roof eave, glass entrance door flanked by four double-hung windows on the right and three double-hung windows on left; second story semi-hexagonal bay, single light window with leaded transom light; right bay has a double-hung window.
2176	c.1902		Two and one-half story, frame residence with front facing gable; projecting pedimented gable, shingled, tripartite window, double-hung; full-width flat roof enclosed porch with extending porch eaves, glass and wood paneled door with sidelights and transoms, band of twenty-light windows, paneled engaged Doric columns flank window bays; second story semi-hexagonal bay with double-hung windows, left bay double-hung window; two-story semi-hexagonal bay on south side with gabled through-the-cornice dormer with cornice end returns.
2178	c.1892		Two and one-half story, brick Romanesque style residence with front facing gable roof with cornice end returns; shed roof enclosed frame entrance porch with glass paneled door; flat roof first story wing with extending eaves, right corner has semi-hexagonal bay has paired straight headed windows, four louvred glass lights; second story has arcade of three eyebrow window heads enframed windows, half-height engaged Doric columns flank windows, round-arched windows have been altered to straight-head, double-hung windows; second story shingled wing has round arched double-hung window; dentil band spans second story; gable has two round arched windows flanked by engaged Doric columns, eyebrow window head, recessed rectangular plans flank window, cornice tops panel. Contributing one-story garage.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Main Street, northwest side only</u>			
2190	c.1900		Two and one-half story, frame residence with front facing gable roof; flat-top hip roof spans first story, two tripartite double-hung windows on first story front facade; second story has two double-hung windows; pedimented gable has tripartite window, single lights with arched tracery, entablature window surround; south side has pedimented gable entrance porch, enclosed, glass paneled door with sidelights; cross gable dormer on south side has Palladian window. Asbestos siding.
2194	c.1890		Two and one-half story, frame residence with front facing gable roof with bargeboard; gable has three windows, single light with diamond patterned tracery with entablature window head; full-width porch has a shed roof with hip roof projection over entrance, square Doric supports, shingled rail, glass and wood paneled door flanked on one side by a double-hung window; first story has two double-hung windows; second story right end bay, recessed, has tripartite double-hung windows and two double-hung windows on the left. Asphalt siding. Contributing one-story garage.
2200	c.1893		Two and one-half story frame residence with front facing gable roof; steep-pitched pedimented gable, shingled, tripartite window, single light center with flanking double-hung windows and shed roof window head; right end bay has two story semi-hexagonal bay with double-hung windows; first story bay windows have entablature surrounds; double three-light doors flanked on one side by double-hung windows; second story has two double-hung windows to the right. Contributing one-story garage.
2202	c.1899		Two and one-half story, frame residence with front facing gable roof; pedimented gable, shingled, four horizontal light windows, cornice head; full-width flat roof porch with projecting eave, fluted Doric columns support entablature, dentils under cornice, stick balustrade, glass paneled door with sidelights; first story tripartite double-hung windows; upper porch stick balustrade on second story with two semi-hexagonal bays with double-hung windows and entablature surrounds, glass paneled porch door on right bay; south side has two story semi-hexagonal bay with gable dormer and cornice end returns. Contributing one-story garage.
2206	c.1900		Two and one-half story, frame residence with front facing gable roof; pedimented gable with modillions under projecting eaves, two double-hung windows with cornice window heads; full-width flat roof porch, enclosed,



<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Main Street, northwest side only</u>			
2206(cont'd)			with extending roof eave, horizontal band of four single-light windows with three vertical light top lights, end Doric pilaster strips; second story semi-hexagonal bay with double-hung windows, glass paneled porch door. Asbestos siding. Contributing one-story gable garage.
2210	c.1900		Two and one-half story, frame residence with front facing gable roof; pedimented gable has modillions under projecting eaves and two double-hung windows; full-width flat roof enclosed porch with extending eaves with modillions, glass paneled door with lighted border and sidelights, tapered Doric pilasters, with capital elaboration, flank window bays, three single light windows with transom; second story has semi-hexagonal bay with double-hung windows, glass paneled porch door. Asbestos siding. Contributing one-story garage.
2212-2214	c.1911-13		Two and one-half story brick Colonial Revival style residence with flat top hip roof; hip roof dormer with paired double-hung windows; full-width flat roof porch, rough-cut stone base and column supports, square porch supports, entablature, glass and wood paneled door, rusticated stone lintels, flanking door on one side is glass and wood paneled door; first story tripartite double-hung window with rusticated stone lintel; second story, three bays have straight-headed double-hung windows with rusticated stone lintels, end bay to north has glass paneled porch door; south side has two-story semi-hexagonal bay. Contributing two-story, brick flat roof garage.
2218	c.1910		Two and one-half story, frame residence with hip roof, brackets under roof eave; pedimented gabled dormer with pair of double-hung windows, brackets under cornice with shingles in pediment; full-width flat roof porch, rough-cut stone base, square Doric supports, glass paneled door flanked on one side by small rectangular leaded window, tripartite first story window, single lights with leaded transom, entablature surrounds; second story semi-hexagonal bay with double-hung windows, glass paneled porch door flanked by double-hung windows; end paneled Doric pilaster strips. Contributing one-story gable roof garage.
2222	c.1908		Two and one-half story, frame Colonial Revival style residence with hip roof with curved brackets and dentils under eaves; hip roof dormer has three double-hung windows, paneled pilaster strips flank; centrally located entrance, four-light wood paneled door with paneled sidelights, flat-roof entrance porch with slender square supports: north end bay has

Of ed Parks & Parkways Thematic Resources:

Parkside Subdivision (East) Historic District, Buffalo, Erie County, NY

Item 3 Page 142

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Main Street, norwest side only</u>			
2222(cont'd)			double-hung straight-headed windows; south end bay has semi-hexagonal bay with double-hung windows; second story semi-hexagonal oriel with double-hung windows; end Doric pilaster strips; one-story wing on north side, flat roof with double-hung window entablature with dentils under cornice spans wing addition. Contributing one-story garage.
2228	c.1914		Two and one-half story, brick and stucco Colonial Revival style residence with side gable roof with exposed rafter-tails under projecting eaves; two hip roof dormers with exposed rafter-tails under projecting eaves with single double-hung window; partial-width shed roof porch with polygonal tapered columns and cut-out patterned rail, wood paneled door with sidelights, pilaster strips flank entrance; first story double-hung windows across facade; second story center bay has pair of small double-hung windows, end bay has two one/one light windows; two-story boxed bay has wood paneled door at ground level, entablature window head, large rectangular windows, twenty-four light' opaque colored glass, flank entrance; entablature with capping cornice spans first story level; second story has three double-hung windows, paneled apron and capping cornice. Contributing one-story garage.
2234	c.1914	99	Two-story, brick "American Four Square" residence with hip roof with projecting eaves, exposed rafter-tails with accented round ends, red tile roof cresting; hip roof dormer with exposed rafter-tails under projecting eaves, red tile roof cresting, four double-hung windows; full-width hip roof wing has exposed rafter-tails under projecting eaves, Doric pilaster strips with capital elaboration flank window bays, three double sash windows; second story has two semi-hexagonal bays, single light windows with leaded transom. Contributing one-story hip roof garage.
2238	c.1914	99	Two-story, brick and stucco "American Four Square" residence with hip roof with exposed rafter-tails under projecting eaves; hip roof dormer with exposed rafter-tails under projecting eaves; full-width hip roof porch wing with three-light wood door and sidelights, tripartite windows, center single light with four-light sidelights, brick first story; second story has a set of paired double-hung windows placed under roof eaves, stucco. Contributing one-story garage.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Main Street, northwest side only</u>			
2248-50	c.1922		Two-story brick commercial building with flat roof with projecting parapet; main entrance at corner with glass paneled with single sidelight; brick piers flank two sets of large paired commercial windows on either side of the entrance; secondary entrance to north, glass paneled, flanked by paired glass commercial windows; Florence Avenue facade has secondary residential entrance, glass paneled with transom, and two commercial entrances flanked by commercial glass windows; stone band course at second story level; second story straight-headed double-hung windows; end bays of building have paired windows and stone band course at parapet level, stone cornice caps parapet.
2254	c.1898		Two and one-half story, frame residence with hip roof with front facing false gable; full-width shed roof porch, rough-cut stone base and porch supports, pediment over stairs, glass and wood paneled wood door with flanking double-hung windows; second story bowed bay with double-hung window; semi-hexagonal bay has double-hung windows; pedimented gable over bowed bay, small square single light window; polygonal third story tower with tent roof with double-hung window flanked by square single light windows; pedimented gable dormer. Aluminum siding. Contributing one-story garage.
2258	c.1920		Two-story, frame "American Four Square" residence with hip roof with projecting eaves; hip roof dormer with projecting eaves, three windows with three vertical lights each; full-width flat roof porch, partially enclosed, rough-cut stone base, tapered paneled square pilaster strips flank horizontal band of double-hung windows with three vertical light windows in top light, end tapered, paneled corner porch support, lighted glass door with glass and wood paneled door on north wall of enclosed porch; clapboard first story; second story semi-hexagonal bay with double-hung windows, three vertical lights in top light, lighted double sash porch door porch rail has vertical cut-outs. Asbestos siding. Contributing one-story hip roof garage.

Costed Parks & Parkways Thematic Resources:

Flatside Subdivision (East) Historic District, Buffalo, Erie County, NY

Item 3 Page 144

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Main Street, northwest side only</u>			
2264	c.1920	100	Two-story, frame "American Four Square" residence with hip roof with projecting eaves; hip roof dormer with projecting eaves had three windows, three vertical lights each; full-width flat roof entrance wing with extending roof eaves, rough-cut stone base, tapered square paneled end pilasters, entablature glass and wood door with plain surround with flanking tripartite window, center single light with double-hung side windows; second story semi-hexagonal bay with double-hung windows, three vertical lights in top light; lighted double sash porch door, shingled, wrought-iron balustrade. Contributing one-story garage.
2268	c.1898	100	Two and one-half story, frame Colonial Revival style residence with hip roof with small brackets and dentils under projecting eaves; pediment gable dormer with tripartite double-hung windows with end paneled pilaster strips support entablature; full-width flat roof porch, rough-cut stone base, fluted Ionic columns support entablature, paneled rail, glass paneled door with leaded sidelights and wood paneled transom, fluted Doric engaged columns flank door; Doric pilaster strips flank entrance and support entablature with dentils under cornice; first story windows, single light with transom; second story center has paired leaded casement window, Doric engaged column mullion, entablature window head; end bays have double sash windows with diamond tracery in top light, entablature window head with dentils under cornice; end fluted Ionic pilaster strips, entablature with dentils. Contributing one-story garage.
2274	c.1912	100	Two-story, frame "American Four Square" residence with hip roof with exposed rafter-tails under projecting eaves; hip roof dormer with exposed rafter-tails under projecting eave; full-width flat roof porch with brackets under projecting eave, paired square tapered supports with column elaboration, stick balustrade glass paneled door flanked by leaded sidelights; first story tripartite double-hung windows; second story has pair semi-hexagonal bays with double-hung windows with entablature surround, lighted porch door in north bay; shingled second story, wrought-iron balustrade on upper porch.

O'sted Parks & Parkways Thematic Resources:

P. Side Subdivision (East) Historic District, Buffalo, Erie County, NY

Item 3 Page 145

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Main Street, northwest side only</u>			
2278	c.1914		Two-story, frame "American Four Square" residence with hip roof with projecting eaves, modillion brackets under eaves; hip roof dormer with projecting eaves, modillion brackets, three double-hung windows; full-width flat roof porch with projecting eaves with modillion brackets, fluted, paired Doric columns, shingled rail, glass paneled door with leaded transom and sidelights; first story tripartite double-hung window; second story semi-hexagonal bay with double-hung windows, boxed bay has lighted double-sash porch door, shingled story. Contributing one-story garage.
2280	c.1911		<u>Non-contributing</u> two-story, frame building total facade alteration; second story straight-sided shingled mansard roof with recessed paired glass sliding doors and wrought-iron balustrade; first story has recessed entrance with four vertical paneled wood door, sidelights, board and batten, tri-partite singlelight casement window with shutters; hip roof dormer.
2284	c.1904		Two-story, frame residence with front facing gable roof with projecting front eaves, bargeboard with flared angular ends, steep-pitched gabled entrance porch, extending eaves, overlapping shingles, eight paneled wood door; first story tripartite casement windows, single lights with shutters; second story hip roof oriel, five single light casement windows, Contributing one-story garage.
2288	c.1902		Two-story, frame and perma-stone residence with hip roof with projecting eaves; pedimented gable has projecting eave with three double-hung windows; full-width flat roof porch with projecting eaves, glass and wood paneled door; first story semi-hexagonal bay with double-hung windows; second story double-sash porch doors, two single-hung windows, top light has glass borders; recessed ends of building on both stories wrought-iron supports and balustrades on both porches. Contributing one-story garage.
2290	c.1902		Two and one-half story, frame residence with one-story frame addition; brick facing; with side gable roof; second story

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Main Street, northwest side only</u>			
2290(cont'd)			gabled through-the cornice dormer with cornice end returns; boxed flat roof bay, pair double-hung windows; dormer has two double-hung windows with cornice window head; hip roof dormer has single-hung window with diamond tracery in top light; one-story flat roof wing projects from residence on first story; south end bay has recessed entrance with three-light wood door with two-light transom; commercial glass front of four single lights, moulded surround with aluminum shed roof. Contributing one-story hip roof garage.
2294-96	c.1922		Two-story brick commercial/residential building with flat roof with stepped parapet; recessed central entrance has two glass paneled doors, two large single light commercial glass windows flank entrance, varigated scalloped band spans commercial front; second story center bay has pair of glass paneled doors, wrought-iron balcony; end bays have tripartite double-hung window; hip roof of red tile spans building; paired triangular knee brackets support roof, small semi-circular arched dormers with louvred windows decorate ends of roof; stepped parapet with rusticated stone capping.
2300	c.1910 c.1930	101	Two and one-half story, frame residence with extending one-story wing, faced with brick; residence has front facing gable roof; partial-width porch, flat roof with extending eaves; four vertical lights over two, single-hung; end Doric pilaster strips; entrance on south side of porch; second story semi-hexagonal bay with double-hung windows; pedimented gable has three double-hung windows with end brackets under projecting gable; one-story projecting wing has flat roof with stepped parapet, round arched entrance with glass paneled door with border lights and sidelights, semi-circular fanlight relieving arch with stone keystone and end stops, two single-hung windows with relieving arch with stone keystone, decorative brick panel below window, central diamond shape enframed by rectangular panel, stone corner stops; stepped parapet has stone cap and corner volutes.



<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Main Street, northwest side only</u>			
2302-04	c.1918	101	Two-story, brick commercial/residential structure, flat roof with parapet; main commercial entrance situated at rounded corner; recessed glass paneled door with transom, metal hood, large single light glass fronts flank entrance with transom lights above, cast-iron front has paneled apron and pilasters flanking entrance; south end bay has recessed glass paneled door; advertising band of trim above windows; cast metal entablature spans entire first story; egg and dart motif below cornice; second story corner windows; center slender double-hung window flanked by two single light windows; square transom lights; Main Street facade second story has band of single-light windows with four-light transoms; cast metal entablature spans entire building; egg and dart and modillions under cornice with stone capped parapet; Oakwood facade first story end bay has glass paneled recessed door flanked by single light commercial glass window with three-light transom; second story has a series of double-hung windows.
2312-16	c.1898	101	Two-story , brick commercial/residential building with one-story wing to the right; flat roof; recessed entrance has glass paneled door; three single-light commercial glass fronts flank entrance; large panel spans first story; rusticated brick piers flank store with paneled transom; entablature spans first story; dentils under cornice; second story has two tripartite double-hung windows; rusticated stone sills and lintel with low-relief quoins; corbel <del>tabel</del> spans building; cornice with dentils one-story wing has recessed glass paneled doors flanked on one side by three single-light glass commercial front. Contributing one-story garage.
2318-20	c.1909		Two-story, brick commercial/residential structure with flat roof with parapet; first story recessed entrance with two glass paneled doors with transoms, flanked by large single-light glass windows, paneled apron, brick piers; south end bay has glass and wood paneled door with entablature; capping cornice spans story; second story semi-hexagonal hip roof oriel with double-hung windows; north end bay has double-hung window with lintel parapet with projecting ends, bossing caps parapet.
2322-24	c.1906		Two-story, brick commercial/residential row building with flat roof with front parapet; first story center bay has double-glass paneled doors flanked by two single light commercial windows: left end bay has glass

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Main Street, northwest side only</u>			
2322-24(cont'd)			and wood paneled door, brick piers flank door and building end; second story has recessed ends; two boxed flat roof oriels with double-hung windows, capping cornice, corbel panel spans entire building; zig-zag molding below parapet top, parapet cap decorated with boss motif.
2328	c.1906		Two-story, brick commercial/residential structure with flat roof with parapet; recessed central entrance, wood door flanked by large single light glass windows; south end bay has glass paneled residential entrance horizontal and vertical glass borders; end brick piers with stone bands; first story spanned by wood entablature with capping cornice; second story has two semi-hexagonal bays with straight-headed double-hung windows; fluted pilasters flank windows with entablature; frieze decorated with three rectangular slender lights; dentils under cornice with stone band at cornice level; parapet has stone panel with inscription 'Ruchte'; parapet capped with bossing.
2334-78	c.1964		<u>Non-contributing</u> brick school building, flat roof; main block is six bays long with each bay having four three-part louvred single light windows on the first and second story.
2384	c.1910	102	Two-story, stone Dutch Colonial Revival style residence with gambrel roof; rough-cut irregular course stone first story; flat roof entrance porch with rounded end brackets under cornice; opaque glass paneled door with leaded sidelights; relieving arch; end bays first story have tripartite double-hung windows with sidelights; with relieving arch; round end brackets under roof eaves; shed roof dormer has center paired double-hung window with flanking double-hung windows. Contributing one-story garage.
2400	c.1909	102	Two and one-half story, stone and frame residence with Craftsman styling; side gable roof with wedge-shaped brackets under extending eaves; shed roof dormer with three nine-light windows; partial-width shed roof porch with extending eaves, rough-cut stone, double glass paneled doors, four-part casement windows with diamond tracery flanking wood panel; first story stone double-hung windows with three vertical top lights with stone relieving arch with keystone; second story three bays each have double-hung windows with shutters; east facade has center chimney of stone; first story has pair shed roof boxed oriels in end bays supported by brackets with exposed brackets under eaves, two double-hung windows; second story double-hung windows with shutters; gable has small rectangular lights.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Main Street, northwest side only</u>			
2434	c.1910	103	Gothic Revival style Church in the 14th-century English tradition; rough cut irregular course stone with basement level of rough-cut stone; east facade has traceried stained-glass window enclosed within recessed Gothic arch of ashlar stone with trefoil tracery and mullions topped with crockets, window leads to first story gabled bay; traceried opaque glass window enclosed with recessed segmental arch with paneled apron; bay and Gothic arched window flanked by ashlar stone buttresses; two set-backs, trefoil panel decorated at its base with petalled flower motif; buttresses topped by gabled shaped heads; end of facade has corner buttresses with gabled heads; parapet ends decorated with petaled flower motif; southeast gabled entrance has four wood doors and trefoil tracery transom enclosed within ogee arch capped by crocket; stone enframement; moulded stone door surround with perpendicular motif in spandrels; Gothic-arched window with moulded stone window head has pair of trefoil traceried windows topped by circular quatrefoil design; end buttress topped by gable heads; stepped gable parapet; the side-aisle walls have Gothic-arched windows with trefoil tracery, buttresses with gable heads; southwest corner has tower with crenalated parapet; string course below parapet corner buttresses is Gothic-arched louvred windows; moulded stone window head; southeast transept arm has Gothic-arched tripartite stained-glass window and trefoil tracery. Lansing and Beierl, Architects.
2450	c.1908	103	Two-story, brick Spanish Renaissance style building with side gable roof of red tile with stepped end parapets; first story north end bay has double-doors; glass paneled with door grilles, stone surround with deeply fluted banded Ionic pilaster strips on pedestal base; diamond motif decorates base entablature with semi-circular pediment above entablature, paneled pilaster strips, center medallion decorated tympanum, inscribed with 'M'; pediment flanked by volutes, end ancones; south end bay replicated this devoid of doors; center has Palladian window with spiral engaged columns, stone circular medallions flank window, stone band course at second story level with three straight-headed windows with decorative metal rain spouts at building ends.
2456	c.1907		Two-story, stone Classical Revival style building with front facing pedimented gable roof; rough-cut irregular course stone with smooth stone basement level with entrance bay and wood door; flat roof entrance hood of wrought-iron supported by paired brackets, cornice, wrought-iron balcony balustrade; end bays have square four-light windows: two-story

0 )ted Parks & Parkways Thematic Resources:

Parkside Subdivision (East) Historic District, Buffalo, Erie County, NY

Item 3 Page 150

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Main Street, northwest side only</u>			
2456(cont'd)			recessed center bay flanked by Ionic columns, center of recessed bay has wood panel decorated with Mason symbol; full entablature with pediment, dentils and modillions under cornice and raking cornice; frieze decorated with words 'F & AM', 'Masonic Lodge,' and No. 835. William Sidney Wicks, Architect of Green & Wicks of Buffalo.
2460-62	c.1925	104	One-story, brick commercial building with flat roof with parapet; three commercial fronts, each have recessed entrance; glass paneled doors with transom flanked by commercial single light glass fronts; brick base; paneled pilasters flank center storefront large panels span each store front; entablature with cornice spans entire first story with extended frieze area, curved brackets with pendant support shed roof of red tile, decorative panels of stucco situated between brackets with brick surround; parapet is decorated with rectangular panels of stucco and stone parapet cap.
2464-68	c.1915		<u>Non-contributing</u> one-story, brick and paneled siding across facade of commercial building.
2474	c.1909	109	Two and one-half story, frame Second Empire style residential/commercial building with straight sided Mansard roof; east facade first story commercial storefront with glass paneled door with transom flanked to right by rectangular window with transom, paneled apron to left is similar window configuration that has been remodeled to four-light window, entablature with capping cornice and end brackets; second story double-hung window; flat roof dormers extend height of roof with double-hung window; Greenfield Street facade has a series of commercial fronts and residential entrances spanned by entablature and capping cornice; second story paired and single double-hung windows; boxed oriel has tripartite window.