

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
472	c.1915		Two and one-half story, frame residence with front facing gable roof with bargeboard supported by triangular knee braces; partial-width porch has tapered square supports with column elaboration, stick balustrade in upper and lower porch; first story glass paneled door, pediment door head in low-relief with flanking multi-light window and transom, Ionic end pilaster strips; second story tripartite window has single light with transom with flanking double-sash porch door; decorative half-timbering in gable with tripartite double-hung window in gable. Contributing one-story hip roof garage.
476	c.1915		Two-story, frame "American Four Square" residence with hip roof with exposed rafter-tails under projecting eaves; hip roof dormer with exposed rafter-tails under projecting eaves and paired nine light windows; partial-width porch has square Doric supports, shingle rail and upper porch stick balustrade, multi-light beveled glass door; first story single double-hung windows flank entrance; second story double-sash door with flanking double-hung windows. Contributing one-story garage.
<u>Crescent Avenue, west side</u>			
484	c.1910		Two-story, frame "American Four Square" residence with hip roof with projecting eaves; hip roof dormer with projecting eaves with paired double-hung windows; full-width hip roof porch has square tapered columns, stick balustrade, two multi-paned double sash door open onto porch; second story two double-hung windows. Contributing one-story hip roof garage.
488	c.1910	92	Two and one-half story, frame residence with front facing gable roof; pedimented gable, shingled with three-partite double-hung windows; partial-width hip roof porch, square posts and modillion brackets in eaves, stick balustrade, off-center glass and wood paneled door with flanking double-hung windows on both sides of porch, right end bay has a double-hung window; second story two double-hung windows. Contributing one story gable roof garage.
492-94	c.1905	92	Two and one half story, frame residence with front facing gable roof with end returns and dentils in cornice, fanlight window in gable; first story left bay has paired double-hung window with flanking entrance, right bay has broken pediment with dentils and paneled pilasters with wood paneled door; second story two double-hung windows; asbestos siding. Contributing one-story garage.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, west side</u>			
496	c.1919	92	Two-story, frame Craftsman style residence with gable roof with wide eaves and oversized brackets; large gabled dormer with three double-hung windows; entranceway with bracketed overdoor on south side of house; full-width gable roof porch has oversized brackets, eight four-light over single pane windows in porch, boxed paneled columns and paneled balustrade with stone foundation. Contributing one-story gable roof garage.
500	c.1916		Two-story, frame "American Four Square" residence with hip roof with projecting eaves with exposed rafter-tails under eaves; hip roof dormer with exposed rafter-tails under projecting eaves with three double-hung windows; full-width hip roof porch wind has brick end piers, horizontal band of eight-light windows enframed within pediment; second story has two sets of paired double-hung windows. Contributing one-story hip roof garage.
506	c.1915		Two and one-half story, frame residence with side gable roof with cornice end returns; full-width shed roof porch with square tapered Doric columns with entablature, stick balustrade, glass and wood paneled door with flanking paired double-hung windows with shutters; second story two double-hung windows with shutters. Contributing one-story gable roof garage.
514	c.1918		Two and one-half story, frame residence with front facing gable roof; pedimented gable, shingled, and has tripartite double-hung windows with bargeboard; full-width flat roof porch with rough-cut stone base, square Doric supports, stick balustrade, glass and wood paneled door with sidelights and flanking tripartite double-hung windows; second story tripartite double-hung windows flanked by glass and wood porch door, wrought-iron balustrade.
552	c.1921	93	Two-story, frame Dutch Colonial Revival style residence with side gambrel roof; full-width hip roof wing has two tripartite double-hung windows, center chimney flanked by a double-hung window on either side; south side has shed roof entrance hood with glass paneled door with sidelights; shed roof dormers have tripartite double-hung windows flanked by single double-hung windows.
556	c.1903	93	Two and one-half story, frame residence with front facing gable roof; pedimented gable, shingled; full-width two-story gable roof with flared eaves, four two-story squared paneled columns support entablature, second story porch enclosed with ten double-hung windows and paneled balustrade.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, west side</u>			
556(cont'd)			stick balustrade on first story, entrance with glass and wood paneled door with sidelights and flanking tripartite window with transom; hip roof dormer with flared eaves on east side. Contributing one-story hip roof garage.
558	c.1900	93	Two and one-half story, frame residence with front facing gable roof; two story full-width gable roof porch, brick base and supports, glass and wood paneled door flanked by two double-hung windows on either side of entrance; second story enclosed porch with horizontal bank of double-hung windows, gable has paired double-hung windows; aluminum and asphalt siding. Contributing one-story hip roof garage.
596	c.1907	94	Two and one-half story, frame residence with front facing gable roof; pedimented gable with overhang has tripartite windows with double-hung windows, shingled; partial-width flat roof porch with wrought-iron balustrade and supports, glass paneled door with left flanking double-hung window; two-story semi-hexagonal bay with sliding glass vertical windows. Contributing one-story gable roof garage.
600	c.1907	94	Two and one-half story, frame residence with side gable roof; partial-width flat roof porch with square Doric supports, stick balustrade, glass and wood paneled door flanked by a second porch door and double-hung window; two story semi-hexagonal tower with conical roof, both stories have double-hung windows with a lunette window in the center of the first story bay; second story porch has stick balustrade and corner supports, a glass and wood paneled porch door and flanking double-hung window. Contributing one-story flat roof garage.
608	c.1911	94	Two and one-half story, frame residence with front facing gable roof; pedimented gable with four double-hung windows and bargeboard; full-width flat roof porch with square supports and stick balustrade, paired double-hung windows with flanking glass paneled door; second story paired double-hung windows with flanking glass and wood paneled porch door, square paneled balustrade with corner posts. Contributing one-story gable roof garage.
612	c.1912		Two and one-half story, frame residence with front facing gable roof; pedimented gable, shingled and has paired double-hung windows; full-width flat roof porch, partially enclosed, brick base and square supports entablature, recessed glass and wood paneled door with flanking horizontal

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, west side</u>			
612(cont'd)			band of four double-hung windows; second story has single double-hung window with flanking glass and wood paneled door, paneled balustrade and corner posts, and canvas awning. Contributing one-story gable roof garage
<u>Crescent Avenue, south side</u>			
634	c.1920		Two-story, frame residence with steep pitched hip roof with projecting eaves; hip roof dormer with projecting eaves and has a pair of double-hung windows; central pedimented gable entrance porch has wrought-iron supports and balustrade, glass paneled door with sidelights with left flanking tripartite window with single lights and right flanking boxed bay with hip roof and paired double-hung windows; second story three double-hung windows; east side has full-width pedimented gable roof; porch has rough-cut stone base and wrought-iron supports and balustrade. Contributing one-story hip roof garage.
644	c.1914	95	Two-story, frame "American Four Square" residence with hip roof with projecting eaves; gabled dormer has bargeboard with flared ends and has a pair of double-hung windows; full-width flat roof porch has wrought-iron supports and balustrade, projecting entrance with glass paneled door with sidelights and flanking tripartite double-hung windows; second story has tripartite double-hung windows and flanking multi-light porch door, stick balustrade and corner posts, shingled. Contributing one-story gable roof garage.
650	c.1916	95	Two-story Bungalow style residence with side gable roof with front extension to form roof of entrance porch, rough-cut stone porch, horizontal band of five double-hung windows, glass paneled door and flanking three double-hung windows; gabled roof dormer has flared eaves, exposed rafter-tails and triangular knee braces under eaves and has three double-hung windows with shutters; shed roof bay on east side of house. Contributing one-story gable roof garage.
654	c.1921	95	Two and one-half story, frame residence with front facing gable roof; pedimented gable, shingled and has a pair of double-hung windows; full-width pedimented gable roof enclosed porch has paneled end pilaster strips, horizontal band of five double-hung windows; second story has two double-hung windows with shutters; east side two-story hip roof porte-cochère, enclosed second story has paired double-hung windows, first story wood paneled door. Contributing one-story hip roof garage.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, south side</u>			
660	c.1923		Two-story, frame residence with hip roof with projecting eaves; hip roof dormer has projecting eaves and tripartite double-hung windows; full-width two-story flat roof enclosed porch, both storys have horizontal band of four double-hung windows with shutters; east side has enclosed entrance porch with deck roof and wood paneled door. Contributing one-story gable roof garage.
670	c.1922		Two-story, frame Bungalow style residence with side gable roof with front extension that provides first story porch roof; has horizontal bane of five double-hung windows, square corner porch supports, wood paneled door flanked by small rectangular leaded-glass sidelights; gable roof dormer has bargeboard and triangular knee braces, tripartite double-hung windows and shingled. Contributing one-story shed roof garage.
674	c.1920		Two-story, frame "American Four Square" residence with hip roof with projecting eaves; hip roof dormer with projecting eaves and has three double-hung windows; full-width flat roof porch has square supports, arched span between supports, rail with small rectangular cut-out pattern, projecting entrance has glass paneled door flanked by two double-hung windows and a multi-light double-sash door flanked by two vertical light windows; second story has a boxed bay with tripartite double-hung windows and flanking multi-light glass porch door, stick and paneled balustrade and paneled corner posts. Contributing one-story hip roof garage.
680	c.1923		Two-story, frame residence with hip roof with central eyebrow dormer window; partial-width semi-circular porch has brackets under eaves, Doric columns and spindle balustrade, round arched multi-light door with flanking double-hung windows; second story two double-hung windows with shutters; west side entrance has semi-circular entrance hood with scalloped border of colored glass. Contributing one-story hip roof garage.
684	c.1922		Two-story, frame Dutch Colonial Revival style residence with front facing gambrel roof; shed roof dormers with exposed rafter-tails under eaves; partial-width hip roof enclosed porch has three double-hung windows; second story has two double-hung windows with shutters; gable has one small double-hung window; east side entrance has glass paneled door under shed roof hood.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, south side</u>			
688	c.1922		Two and one-half story, frame Tudor Revival style residence with side gable roof with curved knee brackets under eaves; large gabled entrance porch has bargeboard with ogee arch formation, paired slender square supports and has glass and wood paneled door; two and one-half story, projecting front facing gable bay has bargeboard with end brackets, first story has a horizontal band of five double-hung windows, second story has segmental arched tripartite double-hung windows, pediment supported by corbel stops caps and gable has a rectangular gable window; first story left bay has tripartite double-hung windows and second story has segmental arched tripartite double-hung windows. Contributing one-story hip roof garage.
690	c.1920		One and one-half story, frame Bungalow style residence with front facing gable roof; shed roof dormer has three double-hung windows with shutters; second story roof projection supported by square Doric supports, eight-light wood paneled door with flanking double-hung windows with shutters on both sides of entrance; projecting gable eave has bargeboard and triangular knee braces, gable sides have exposed rafter-tails and has a pair of double-hung windows with shutters. Contributing one-story gable roof garage.
696	c.1919		Two-story, frame residence with hip roof with projecting eaves; hip roof dormer has projecting eaves and has a pair of double-hung windows; full-width flat roof porch has square supports, paneled balustrade, glass paneled door flanked by leaded-glass sidelights and right bay has a tripartite double-hung windows; second story has a semi-hexagonal bay with double-hung windows and flanking glass paneled porch door, stick balustrade. Contributing one-story hip roof garage.
700	c.1920		Two-story, frame "American Four Square" residence with hip roof with exposed rafter-tails under projecting eaves; hip roof dormer with exposed rafter-tails under projecting eaves; full-width deck roof porch has square supports, rough-cut stone base, paneled rail, projecting eaves with exposed rafter-tails, arched span between supports, glass paneled door with leaded sidelights with flanking tripartite double-hung windows; second story shingled, tripartite double-hung windows with left flanking glass paneled porch door, wrought-iron supports and balustrade. Contributing one-story hip roof garage.

Historic Parks & Parkways Thematic Resources:
 Parkside Subdivision (East) Historic District, Buffalo, Erie County, NY

Item 3 Page 44

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, south side</u>			
704	c.1923		Two-story, frame "American Four Square" residence with hip roof with projecting eaves; hip roof dormer with projecting eaves and has three double-hung windows; full-width flat roof porch partially enclosed has a tripartite double-hung windows, brick, with flanking recessed glass and wood paneled door with sidelights; second story has boxed bay with tripartite double-hung windows with flanking glass paneled porch door, wrought-iron balustrade. Contributing one-story hip roof garage.
706	c.1923		Two-story, frame "American Four Square" residence with hip roof with projecting eaves; hip roof dormer has projecting eaves and has four small vertical light windows; full-width flat roof porch partially enclosed has rough-cut stone base and rail, horizontal band of six double-hung windows and flanking recessed entrance with glass paneled door with sidelights, Doric porch supports; second story has tripartite double-hung windows with flanking multi-light porch door, wrought-iron balustrade; east side has a trellised porte-cochère. Contributing shed roof garage.
718	c.1915		Two and one-half story, frame residence with side gable roof; gabled roof dormer with bargeboard and has three double-hung windows; partial-width flat roof enclosed porch has a horizontal band of eight double-hung windows with glass and wood paneled porch door on side with flanking double-hung windows and a tripartite double-hung windows in left bay; second story has a single double-hung window in the left bay, a louvred glass porch door flanked by a pair of double-hung windows. Contributing one-story gable roof garage.
722	c.1957	96	<u>Non-contributing</u> one and one-half story frame residence.
728	c.1916	96	Two and one-half story, frame residence with side gable roof with end triangular knee braces; partial-width gabled enclosed porch has end tapered supports with column elaboration, paired double-hung multi-light windows, flanking glass paneled door with entablature surround, left bay has a hip roof boxed bay with double-hung windows under projecting eaves with exposed rafter-tails; second story has two sets of paired double-hung windows at end bays with central small double-hung window.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, south side</u>			
732	c.1915	96	Two and one-half story, frame Tudor Revival style residence with front facing gable roof with cornice end returns; multi-gabled facade; gabled entrance porch has round arched entrance, round arched single light vertical planked door, stick styling in gable; first story has a tripartite double-hung windows; first story wing has a set of paired double-hung windows; gabled second story with cornice extension and tripartite double-hung windows; decorative half-timbering in gables; main gable has a set of paired double-hung windows. Contributing one-story hip roof garage.
736	c.1924		Two-story, frame "American Four Square" residence with hip roof with projecting eaves; hip roof dormer has projecting eaves and has three double-hung windows; full-width flat roof porch partially enclosed with brick pier supports, recessed entrance has glass paneled door and sidelights, each having horizontal and vertical borders, with flanking tripartite with paired nine-light casement windows and leaded transoms; second story has tripartite double-hung windows with flanking multi-light porch door, wrought-iron balustrade. Contributing one-story gable roof garage.
742	c.1922		Two-story, frame "American Four Square" residence with hip roof with projecting eaves; hip roof dormer with projecting eaves; full-width hip roof porch partially enclosed has modern picture window; recessed entrance has three vertical light door flanked by sidelights, square Doric supports; second story has boxed bay with double-hung windows and flanking four vertical light porch door; porte-cochère on east side. Contributing one-story gable roof garage.
748	c.1922		Two and one-half story, frame Dutch Colonial Revival style residence with side gambrel roof with flared ends and cornice end returns; shed roof dormer, overscale, has small paired four-light square windows flanked by a double-hung window with shutters at each end; pedimented gable entrance porch has multi-light glass door flanked by multi-light sidelights, and has segmental farlight window in tympanum; first story has four-part multi-light windows with shutters.
752	c.1922	97	Two and one-half story, frame Dutch Colonial Revival style residence with side gambrel roof with flared ends and cornice end returns; shed roof dormer, overscale, has small paired four-light square windows flanked by a

Unmsted Parks & Parkways Thematic Resources:
Parkside Subdivision (East) Historic District, Buffalo, Erie County, NY

Item 3 Page 46

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, south side</u>			
752(cont'd)			double-hung window with shutters at each end; pedimented gable entrance porch has multi-light glass door flanked by multi-light sidelights, and has segmental fanlight window in tympanum; first story has four-part multi-light windows with shutters. Contributing one-story gable roof garage.
756	c.1923	97	Two and one-half story, frame Dutch Colonial Revival style residence with front facing gambrel roof with flared ends and projecting eaves; over-scale shed roof dormers on east and west side has three double-hung windows; hip roof first story wing has three multi-light double-hung windows; second story, north side has two double-hung windows with a single double-hung window in top of gambrel; first story east side has porch entrance with false gable, square Doric supports with entablature and glass and wood paneled door with flanking double-hung windows. Contributing one-story shed roof garage.
762	c.1923	97	Two-story, frame "American Four Square" residence with hip roof with exposed rafter-tails under projecting eaves; hip roof dormer with exposed rafter-tails under projecting eaves and has two double-hung windows; partial-width hip roof porch has exposed rafter-tails under projecting eaves, square Doric supports and spindle balustrade, round arched multi-light door with flanking double-hung windows with square-headed surrounds at end bays; second story has two double-hung windows with shutters; west side has pedimented entrance porch with square Doric supports and glass paneled door. Contributing one-story gable roof garage.
766	c.1923		Two and one-half story, frame Dutch Colonial Revival style residence with front facing gambrel roof; shed roof dormers on east and west side has two double-hung windows flanking a small double-hung window; roof has flared ends and projecting eaves; hip roof first story enclosed porch has three double-hung windows with shutters; second story gambrel side has two double-hung window with shutters and has a small double-hung window in top of gable; east side hip roof entrance porch with wrought-iron supports and has glass and wood paneled door flanked by tripartite multi-light windows. Contributing one-story gable roof garage.
772	c.1919		Two and one-half story residence with front facing clipped gable roof; shed roof dormer on east and west sides have paired double-hung windows;

Assisted Parks & Parkways Thematic Resources:
Parkside Subdivision (East) Historic District, Buffalo, Erie County, NY

Item 3 Page 47

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, south side</u>			
772(cont'd)			partial-width flat roof enclosed porch has tripartite double-hung windows with multi-light transom, Doric end pilaster strips, porch side has glass paneled door with double-hung sidelights and transom; second story has band course, double-sash porch doors with flanking double-hung windows, square headed surrounds; shingled clipped gable and has three double-hung windows, wrought-iron balustrade. Contributing one-story gable roof garage.
776	c.1922		Two-story, frame "American Four Square" residence with hip roof with exposed rafter-tails under projecting eaves; hip roof dormer with exposed rafter-tails under projecting eaves and has three double-hung windows; full-width hip roof porch partially enclosed has a horizontal band of five double-hung windows, recessed entrance has square corner supports, glass and wood paneled door; second story has two sets of paired double-hung windows with shutters.