

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
10	c.1897		Two-story, frame Colonial Revival style residence with hip roof with projecting eaves; pedimented gable dormer with three double-hung windows; partial-width serpentine shaped roof porch with fan arched decoration, Doric columns, wood paneled door with flanking sidelights, right end bay has a double-hung window; second story has two sets of paired double-hung windows with plain surrounds and shutters; fluted Ionic pilaster corner boards; oriel on south wall has large turned finial above its roof.
12	c.1897		Two-story, frame Colonial Revival style residence with hip roof with projecting eaves; pediment gable dormer with end returns, Palladian window and fluted Ionic pilaster strips; full-width flat roof porch is supported by fluted Ionic columns, stick balustrade, wood paneled door with flanking sidelights, end bays have double-hung windows; second story has two sets of paired double-hung bay windows with denticulated cornices; fluted Ionic pilaster corner boards.
16	c.1908		Two-story, frame "American Four Square" residence with hip roof with projecting eaves; pediment gable dormer has baroque console decoration and a pair of double-hung windows with plain surround; full-width flat roof porch, rough-cut stone base and pedestals, tapered square Doric columns, stick balustrade, wood paneled door with flanking sidelights, right bay window with double-hung windows; left corner has a flat roof one-story circular tower with double-hung windows; second story right bay window with three double-hung windows and plain surrounds, left bay has a tripartite window with slender sidelights. Contributing one-story garage.
24	c.1895		Two and one-half story, frame residence with front facing gable roof; pediment gable with flared eave at base, shingled, has pair of double-hung windows; full-width shed roof porch with pediment gable above porch entrance, shingled base, wrought-iron balustrade, Doric columns support entablature, glass and wood paneled entrance off center with flanking double-hung windows on both sides of door; second story left bay with double-hung windows, right bay double-hung window; band of trim below roof eave. Contributing one-story garage.
30	c.1897		Two-story, frame residence with hip roof with modillion brackets under eaves; full-width flat roof porch with modillion brackets under eaves, rough-cut stone base, wrought-iron columns support porch, glass and wood paneled door;

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
30(cont'd)			semi-hexagonal bay with double-hung flank entrance; second story has two semi-hexagonal bays with double-hung windows with fluted pilasters and denticated cornices; corner boards are narrow fluted Ionic pilasters. Asbestos siding. Contributing one story hip roof garage.
32	c.1898		Two and one-half story, frame residence with front facing gable roof; pedimented gable with flared eave at base with large supporting brackets, paired double-hung windows; full-width flat roof porch with rough-cut stone base and pedestals, fluted Ionic columns, stick balustrade, off-center entrance with glass and wood paneled door, right bay single double-hung window and left tripartite double-hung window; second story porch with paneled balustrade and two semi-hexagonal bays with double-hung windows, metal awning covers right bay window. Asbestos siding.
34	c.1896	85	Two and one-half story, frame Queen Anne style residence with cross-gable roof; cantilevered half-story gable with Palladian window and three patterns of shaped wood shingles; south elevation has a gambrel roof gable with patterned shingles above a two-story window bay; a unique feature is the second story oriel window which emerges from the roof as part of an octagonal tower capped with a sectioned metal dome and 'mortar board' termination; the tower has a pedimented window, panels of patterned shingles and classical cornice; irregularity reflected in plan and roof of porch; full-width shed roof with pediment gable above stairs, rough-cut stone base, wrought-iron balustrade and supports, entablature, glass and wood paneled door, boxed and flanked on one side by two double-hung windows; second story, left bay has semi-hexagonal bay with double-hung windows, right bay has a single double-hung window. Contributing one-story gable roof garage.
38	c.1907	85	Two and one-half story, frame residence with front facing gable roof; pedimented gable with eave overhang, boxed bay with tripartite double-hung window with pagoda roof; partial-width flat roof porch with rough-cut stone base and pedestals, Doric columns and entablature, porch continues around south side with main entrance with glass and wood paneled door; right bay has two-story semi-hexagonal bay with double-hung windows with leaded and stained-glass transoms; first story left bay has a single double-hung window; second story, left bay has a single double-hung window. Contributing one-story gable roof garage.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
44	c.1908	85	One and one-half story Bungalow style residence with side gable with long slope providing cover for a facade porch with supporting round columns; recessed shed roof dormer has three double-hung windows; first story has center wood and glass paneled entrance door with flanking French doors with multi-light glass, wrought-iron balustrade.
48	c.1891		Two and one-half story, frame Queen Anne style residence with cross-gable; cantilevered half-story gable with Palladian window; two and one-half story chamfered corner tower with conical roof with finial; partial-width shed roof porch with pediment gable above stairs, glass and wood paneled door; two story semi-hexagonal bay with double-hung windows; block panel in frieze. Asbestos siding.
54	c.1895		Two and one-half story, frame Queen Anne style residence with cross-gable; pedimented gable roof, shingled and Palladian window with vertical accent, fluted Ionic pilasters and leaded glass fanlight, oval leaded-glass window has carved wood cresting of ribbons and leaves; north facade has octagonal tower with iron finial, tall ribbed chimney pots; full-width and partial-side wrap-around porch, with rough-cut stone base, Ionic column supports, paneled balustrade, wrought-iron balustrade upper porch, north side awning roof on north side porch; two story semi-hexagonal bay with double-hung windows; first story, glass and wood paneled door with flanking double-hung windows. Contributing one-story garage. Asbestos siding.
64	c.1904		Two and one-half story, frame residence with front facing gable roof; pedimented gable with three double-hung windows with entablature surround; full-width, two-story shed roof porch, enclosed, rough-cut stone base, glass paneled door flanked on one side by horizontal band of four double-hung windows and right bay has a single double-hung window; second story horizontal band of seven double-hung windows; aluminum siding. Contributing one-story garage.
68	c.1909		Two and one-half story, frame residence with front facing gable roof; pedimented gable with projecting eaves, paired double-hung windows; full-width deck roof porch, square supports, bracketed cornice, stick balustrade, glass and wood paneled entrance door with flanking sidelights, tripartite window bay with double-hung windows and sidelights; second story with two semi-hexagonal bays with double-hung windows and center upper porch entrance door, stick balustrade. Contributing one-story garage.

Olmsted Parks & Parkways Thematic Resources:

Side Subdivision (East) Historic District, Buffalo, Erie County, NY

Item 3 Page 23

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
74	c.1908		Two-story, frame Colonial Revival style residence with hip roof with projecting eaves with modillion brackets; hip roof dormer with projecting eaves, Doric pilaster strips, paired double-hung windows; full-width flat roof porch with rough-cut stone base and pedestals, Ionic column supports, stick balustrade and entablature, glass and wood paneled entrance door with left flanking small rectangular window and right flanking tripartite double-hung windows; second story right bay boxed with double-hung windows, left bay has a single double-hung window; fluted Ionic pilaster corner boards. Contributing one-story hip roof garage.
76	c.1907		Two-story, frame Colonial Revival style residence with hip roof with projecting eaves with three modillion brackets, hip roof dormer with projecting eaves, Doric pilaster strips, paired double-hung windows; full-width flat roof porch with rough-cut stone base and pedestals, Doric column supports, stick balustrade and entablature, glass and wood paneled entrance door with sidelights and flanking tripartite double-hung windows; second story two semi-hexagonal bays with double-hung windows, fluted pilaster corner boards. Contributing one-story hip roof garage.
78	c.1913		One and one-half story, brick and stucco Bungalow style residence with side gable with long slope roof; shed roof wing with single double-hung windows flanking chimney and left bay has tripartite double-hung windows; second story, stucco with tripartite double-hung window; projecting exposed 'purling' support bargeboard on gable; north side entrance porch with flat roof with scroll brackets.
86	c.1911		Two-story, brick and frame "American Four Square" residence with hip roof with wide projecting overhang with exposed rafter-tails; hip roof dormer with projecting overhang and exposed rafter-tails, paired double-hung windows; full-width flat roof porch, rough-cut stone base and pedestals, Doric columns support entablature, stick balustrade, glass and wood paneled entrance door with flanking tripartite double-hung windows with leaded transoms and left flanking single double-hung window; second story two semi-hexagonal bays with double-hung windows. Contributing one-story hip roof garage.
90	c.1910	86	Two-story, frame "American Four Square" residence with hip roof with projecting eaves, exposed rafter-tails; hip roof dormer with projecting eaves with exposed rafter-tails, three double-hung windows; full-width

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
90(cont'd)			flat roof porch with projecting eaves, rough-cut stone base and pedestals, diamond pattern balustrade, Doric columns support entablature, glass and wood entrance door with sidelights with flanking tripartite double-hung window with transom, right bay small rectangular window; second story two boxed bays with double-hung windows with transoms. Contributing one-story hip roof garage.
96	c.1898	86	Two and one-half story, frame residence with front facing gable roof; pedimented gable with projecting overhang, Palladian window with keystone; full-width rough-cut stone porch base with wrought-iron balustrade; first story right bay has a single double-hung window flanking wood paneled door, two-story boxed bay with center single-light with leaded glass transom with flanking slender double-hung windows with leaded and stained glass on both storys; second story right bay has a single double-hung window with flanking wood and glass paneled door with wrought-iron balcony. Contributing one-story garage.
98	c.1904	86	Two-story, frame Colonial Revival style residence with hip roof with projecting eaves; hip roof dormer with projecting eaves, paired double-hung windows; full-width flat roof porch with rough-cut stone base, stick balustrade, Doric columns support entablature; first story off-center glass and wood paneled entrance door with sidelights and flanking large single-light window with leaded transom; second story two sets of paired double-hung windows with entablature surrounds. Contributing one-story garage.
104	c.1904		Two and one-half story, frame residence with front facing gable roof with pedimented gable with overhanging eaves with Palladian window and shingled; first story flat roof enclosed wing with projecting overhang and exposed rafter-tails and horizontal band of four single-hung windows with transom; second story two boxed bays with center single light window with transom and slender sidelights under projecting eaves with three brackets. Contributing one-story garage.
108	c.1905		Two and one-half story, frame residence with front facing gable roof with pedimented gable with projecting eaves, shingles, tripartite double-hung windows with entablature surround; full-width shed roof with pediment above stairs, rough-cut stone base, Doric columns support entablature, stick balustrade; first story off-center glass and wood paneled entrance bay with flanking double-hung windows on both sides; second story two semi-hexagonal bays with double-hung windows; aluminum siding. Contributing one-story garage.

Olmsted Parks & Parkways Thematic Resources:

Side Subdivision (East) Historic District, Buffalo, Erie County, NY

Item 3 Page25

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
110	c.1904		Two and one-half story, frame residence with front facing gable roof; pediment gable with projecting eaves and Palladian window; full-width deck roof porch with rough-cut stone base, wrought-iron supports and balustrade; first story glass and wood paneled door with flanking semi-hexagonal bay with double-hung windows; second story off-center glass and wood paneled door with right flanking double-hung window and left flanking semi-hexagonal bay with double-hung windows, wrought-iron balustrade; asbestos siding.
114	c.1902		Two-story, frame residence with Colonial Revival style features; hip roof with projecting overhang; hip roof dormer, paired, pedimented gable with end returns and single double-hung windows; first story off-center entrance glass and wood paneled door with classical scroll broken-pediment over doorway, left flanking double-hung window, right flanking corner two-story porch with stick balustrade and Ionic column supporting entablature; second story two sets of paired double-hung windows and corner porch. Contributing one-story garage.
126	c.1910		Two and one-half story, frame residence with front facing gable roof; pedimented gable has brackets under cornice and raking cornice; partial-width flat roof porch, rough-cut stone base with corner stair access porch with wrought-iron balustrade and supports entablature with dentils and modillion blocks under cornice, recessed entrance with wood paneled door; first story has two sets of tripartite double-hung windows; second story has two large double-hung windows. Contributing one-story garage.
130	c.1910	87	Two and one-half story, frame residence with side gable roof; pedimented gable dormer with cornice end returns, arched tracery in top light of double-hung window; full-width hip roof porch with rough-cut stone base, Doric columns support entablature, leaded glass paneled door; first story single-light window with leaded and stained-glass transom and left side semi-hexagonal bay with double-hung windows with entablature surround; second story boxed bay with double-hung window and semi-hexagonal bay with double-hung windows.
134	c.1909	87	Two-story, frame residence with Craftsman style features; steep pitched hip roof with projecting eaves, exposed rafter tails with curved ends and brackets with pendants under

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
134(cont'd)			eaves; hip roof dormer has exposed rafter-tails under extending eaves, pair of double-hung windows; partial-width flat roof porch has square rough-cut stone supports, spindle balustrade, wood paneled door; first story tripartite double-hung windows and semi-circular bay has eighteen light casement window; second story small square leaded window flanked by double-hung windows. Contributing one-story garage.
138	c.1909	87	Two and one-half story, frame residence with Craftsman style features; side gable roof with hip roof dormer with exposed rafter-tails under eaves, rectangular multi-light window; full-width hip roof porch with square supports, paneled rail with cut-out balustrade, pair of semi-hexagonal bays with double-hung windows and rectangular leaded glass, paneled apron, bay to north has center glass paneled door; second story gabled bay has tripartite double-hung window with entablature heads, gable has rectangular multi-light windows; north side has gabled entrance porch, glass paneled door with sidelights. Contributing one-story hip roof garage.
140	c.1910		Two-story, frame "American Four Square" residence with hip roof with exposed rafter-tails under projecting eaves; hip roof dormer has exposed rafter-tails under eaves and four rectangular windows; "L" shaped hip roof porch has gabled projection, bargeboard with square decorative motifs, paired square supports with column elaboration, stick balustrade, glass paneled door with sidelights; first story multi-light double sash doors and multi-light porch door flank rectangular leaded window; second story, shingled and two boxed bays with paired double-hung windows. Contributing one-story gable-roof garage.
146	c.1907		Two and one-half story, frame residence with front facing gable roof; pedimented gable has recessed tripartite window, double-hung with end half-fluted Doric pilaster strips; full-width flat roof porch has Doric columns, spindle balustrade, glass paneled door flanked by leaded-glass rectangular window; first story single light with leaded transom;

Olmsted Parks & Parkways Thematic Resources:

Side Subdivision (East) Historic District, Buffalo, Erie County, NY

Item 3 Page 27

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
146(cont'd)			second story semi-hexagonal bay with double-hung windows, paneled surround; brackets with pendants and dentils under projecting gable eaves. Contributing one-story gable roof garage.
150	c.1906		Two and one-half story, frame residence with front facing gable roof; pedimented gable has tripartite double-hung window with brackets under gable eaves and semi-circular pediment over center window; full-width flat roof porch with wrought-iron supports and balustrade, glass paneled door with flanking double-hung window on the left and a large multi-light window flanking on the right; second story, semi-hexagonal bay with double-hung windows and right bay has a double-hung window. Contributing one-story gable roof garage.
154	c.1906		Two-story, frame "American Four Square" residence with hip roof with projecting eaves; hip roof dormer has a pair of double-hung windows and projecting eaves; full-width flat roof porch has square Doric supports and spindle balustrade, glass and wood paneled door with flanking three double-hung windows; second story right bay has a set of paired double-hung windows and left bay has bowed bay window with double-hung windows and leaded sidelights; dentils and bracket under roof eaves. Contributing one-story hip roof garage.
156	c.1910		Two-story, frame Colonial Revival style residence with hip roof with projecting eaves with exposed rafter-tails and brackets under eaves; hip roof dormer with flared eaves, exposed rafter-tails and a pair of double-hung windows; full-width flat roof porch with entrance projection, rough-cut stone base, square Doric supports and spindle balustrade; glass paneled door with leaded sidelights and tripartite double-hung windows; second story two semi-hexagonal bay with entablature window head, upper porch door located in center bay of the small semi-hexagonal bay, wrought-iron balustrade. Contributing one-story hip roof garage.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
162	c.1895		Two and one-half story, frame residence with cross gable roof; pedimented gable has end returns and Palladian window; full-width flat roof porch with square Doric supports and stick balustrade, glass and wood paneled door with double-hung sidelights; first story flanking entrance are two double-hung windows; second story has two double-hung windows with capping cornice window heads. Contributing one-story garage. Asbestos siding.
164	c.1895		Two-story, frame "American Four Square" residence with hip roof; hip roof dormer with tripartite double-hung windows; full-width hip roof porch with rough-cut stone base, wrought-iron supports and balustrade, glass and wood paneled door with flanking pair of double-hung windows; second story two sets of paired double-hung windows with frieze decorated with garland motifs; end fluted Ionic pilaster strips.
168	c.1909		Two and one-half story, Dutch Colonial Revival style residence with side gambrel roof with extending eaves; semi-circular portico has Doric columns, spindle balustrade and dentils under crowning cornice, glass paneled door with sidelights; brick first story with dentils under second story flared ends; first story single-light windows with four-light transoms; second story shingled, center bay opens on to upper porch, glass and wood paneled door and wrought-iron balustrade, flanking double-hung windows. Contributing one-story garage.
176	c.1907		Two and one-half story, frame Colonial Revival style residence with side gable roof with cornice end returns; pedimented gable dormers with cornice end returns with double-hung windows; gable ends have quarter round windows; partial-width pedimented entrance porch has cornice end returns and ogee-shaped cut-out in tympanum, paired Doric columns support entablature, rough-cut stone base, glass paneled door with leaded sidelights; first and second story double-hung windows with entablature with cornice window surrounds; gable end chimney. Contributing one-story hip roof garage.
194-96	c.1925		Three-story, brick U-shaped apartment building with flat roof with classical details, basement level has paired, square double-hung windows with relieving arch; front facades have pairs, of tripartite double-hung windows; third story belt course, entablature with dentils under cornice, stepped parapet with center and end shield motifs; main entrance have marble surround, paneled pilaster strips supporting entablature with crowning cornice; panel above door inscribed with "Crescent"; window over entrance has pediment window hood, marble surround with base volutes and double-hung windows.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
206	c.1912	88	Two-story, frame residence with Craftsman style features; hip roof with exposed rafter-tails under extended eaves; gable roof dormer with barge-board and end bracket supports, stick styling in gable and paired double-hung windows; full-width shed roof porch partially enclosed with pediment above entrance stairs with stick styling, square supports with curved bracket supports, stick balustrade, glass paneled door, tripartite porch window with sidelights; first story brick; second story shingled with flared end projections, boxed and semi-hexagonal bays with double-hung windows and entablature surrounds. Contributing one-story garage.
210	c.1909	88	Two and one-half story, Colonial Revival style residence with front facing gable roof with modillions and dentils under eaves; pedimented gable has tripartite window with diamond tracery in top light with semi-circular arch with fan motif above; end fluted Doric pilaster strips; side pedimented gable dormers; partial-width flat roof porch has rough-cut stone base and pedestals, Ionic fluted columns, dentils under eaves, glass paneled door with leaded sidelights, pilasters support entablature with dentils; first story, single light window with leaded transom flanks door, and bowed bay with double-hung windows flank door on the left; second story has a pair of bowed bays with double-hung windows flanking an elliptical window with square frame; Contributing one-story garage.
216	c.1912	88	Two and one-half story, brick Colonial Revival style residence with side gable roof; pedimented dormers with cornice end returns, round arched windows, arched lights in top light with eight-lights in bottom light; pedimented entrance porch has cornice end returns, Doric columns, louvre glass paneled door has leaded sidelights, semi-circular fanlight first story tripartite windows, double-hung windows, center with sidelights, relieving arch; second story has small rectangular windows, end shutters in center, flanked by double-hung windows with shutters; stylized dentils under roof cornice.
220	c.1905		Two and one-half story, frame residence with front facing gable; pedimented gable has end brackets, supporting entablature with cornice, shingled low relief boxed bay with entablature with cornice, three rectangular windows with diamond-shaped tracery in each light, terra-cotta chimney pots; partial-width flat roof porch has square Doric supports, projecting entrance has glass and wood paneled door, wrought-iron balustrade; two-story semi-hexagonal bays with double-hung windows; second story has right bay, double-hung window. Contributing one-story gable roof garage.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
224	c.1888		Two and one-half story, frame residence with Queen Anne features; gable-on-hip roof; gable has extended eave with end brackets, paired square windows with four-lights upper border, shed roof second story boxed bay on north side supported by curved brackets; full-width hip roof porch with stick balustrade and supports, glass and wood paneled door; first story paired double-hung windows flank entrance; second story has paired double-hung windows. Contributing one-story gable roof garage.
230	c.1905		Two and one-half story, frame Colonial Revival style residence with side gable roof; pedimented gable dormers, paneled pilaster strips flank a double-hung window; full-width flat roof porch has Doric columns, spindle balustrade, glass paneled door; first story double-hung windows with entablature surrounds flank entrance; second story has a pair of semi-hexagonal bays with double-hung windows, center small rectangular leaded windows with entablature surround.
232	c.1896		Two and one-half story, frame residence with Queen Anne features; front facing gable; pedimented gable has projecting eaves decorated with modillions blocks, bargeboard with corner brackets, four-part window, rectangular with vertical tracery, north side has second story gable porch with curved bracket supports, Doric column supports; full-width porch has stone base, fluted Doric columns, double single-light wood paneled doors flanked by rectangular stained-glass windows; first story and second story double-hung windows. Contributing one-story gable garage.
234	c.1931		Two and one-half story, brick Colonial Revival style apartment building with flat topped hip roof with modillions under eaves, glass paneled door with stone surround, broken pediment with pineapple center; frieze inscribed with "Oakwood"; second story round-arched windows over entrance with ten-light double-sash window with round arched transom, keystone; basement paired square double-hung windows; first and second story paired double-hung windows.
238	c.1900		Two and one-half story, frame Queen Anne style residence with hip roof; front facing gabled facade; pedimented gable has Palladian window; glass and wood paneled door with slender leaded sidelights, concave entrance hood; first story double-hung windows; second story tripartite window; center window top light has round arched tracery, double-hung side windows; two and one-half story tower, semi-hexagonal first and second story with polygonal third story and roof with double-hung windows. Contributing two-story gabled garage.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
252	c.1895		Two and one-half story, frame residence with front facing gable; pedimented gable has palladian window; full-width flat roof enclosed porch main entrance flanked by three double-hung windows on each side with Doric pilaster strips; second story semi-hexagonal bay and triangular bay with double-hung windows and center bay elliptical window, Contributing one-story garage. Asbestos siding.
254	c.1908		Two-story, frame "American Four Square" residence with hip roof with exposed rafter-tails under extending eaves; hip roof dormer with exposed rafter-tails under eaves, prism shaped lights in top light of paired double-hung windows; full-width hip roof porch with pedimented gable above stair, projection supported by end brackets, paired tapered square supports, shingled rail, rough-cut stone base, glass paneled door; first story single light window with leaded transom, entablature surround; second story double-hung windows. Contributing one-story hip roof garage.
258	c.1909	89	Two and one-half story, frame Craftsman style residence with side gable roof with cornice end returns; over-scale pedimented gable caps second story, gable supported by curved triangular knee braces, ogee-shaped cut-out in tympanum area; full-width flat roof porch enclosed has horizontal band of four windows, three square lights over two rectangular lights, spindle balustrade; pilaster strips flank with curved capitals, glass and wood paneled door with transom and sidelights, clapboard; second story shingled, two double-hung windows, paneled pilaster strips and paneled frieze with capping cornice window head. Contributing one story garage.
260	c.1894	89	Two and one-half story, frame Shingle style residence with side gable with porch under extending main roof line, rough-cut stone base and supports, glass and wood paneled door; first story has a pair of double-hung windows with leaded transom, large single light window with leaded transom; second story tower has brackets under eaves with horizontal band of double-hung windows with leaded transoms, polygonal dormer has double-window flanked by square single light windows. Contributing one-story garage.
268	c.1913	89	Two-story, frame and stucco "American Four Square" residence with hip roof with extending eaves; hip roof dormer has tripartite double-hung window; full-width flat roof wing has paneled end pilaster strips

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
268(cont'd)			flanking three sets of three double-hung windows with transoms; second story belt course, center bay decorative panels with flanking double-hung windows; north side has two and one-half story gabled bay with wood paneled door with sidelights, square entrance hood with decorative curved brackets of wrought-iron. Contributing one-story garage.
280	c.1909		Two-story, frame residence with side gable roof; south end has wood paneled door flanked by rectangular six-light window; second story front-facing projecting gabled bay, three sets of paired double-hung windows, circular window with tracery in gable, north end has recessed entrance, double-sash door with leaded transom and double-hung windows; front-facing projecting gabled bay, paired double-hung windows flanked by square nine-light windows, circular window with tracery in gable.
326	c.1909		Two and one-half story, frame residence with Craftsman style features; side gable roof with exposed rafter-tails under eaves; hip roof dormers with exposed rafter-tails and multi-pane window; full-width hip roof porch with exposed rafter-tails, rough-cut stone base, square Doric supports, entrance has glass and wood paneled door with leaded sidelights; first story double-hung windows; second story windows placed under roof eaves, center double-hung window flanked by double-hung windows with shutters. Contributing one-story garage.
330	c.1906		Two-story, frame "American Four Square" residence with hip roof; pedimented gable dormers with double-hung window; full-width flat roof porch has square Doric supports and stick balustrade, glass paneled door with stained-glass sidelights, right bay has a double-hung window and left single-light window with leaded transom; second story has two semi-hexagonal bays with double-hung windows.
334	c.1908		Two and one-half story "American Four Square" residence with hip roof; hip roof dormer has three double-hung windows with projecting overhang; full-width flat roof porch with rough-cut stone base, fluted Doric columns, clapboard rail, partial porch enclosure has two twelve light windows with three light transoms, glass and wood paneled door; second story has double-hung windows, asphalt siding. Contributing one-story garage.
338-40	c.1929	90	Two, two-story, brick Italian Renaissance style apartment buildings with flat-top hip roof with red ceramic tiles; symmetrical facade; entrance accented by Doric pilasters supporting entablature; frieze decorated by

Olmsted Parks & Parkways Thematic Resources:

F Side Subdivision (East) Historic District, Buffalo, Erie County, NY

Item 3 Page 33

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
338-40(cont'd)			swag motifs; multi-light door with multi-light sidelights; cellar level has paired three-light windows with relieving arch; first and second story tripartite windows in end bays, double-hung lights with relieving arch on first story; center second story round arched window with relieving arch and keystone; semi-circular fanlight over double-hung window with shutters.
352	c.1904	90	Two-story, frame "American Four Square" residence with hip roof with projecting eaves; hip roof dormer has three rectangular windows; full-width hip roof porch has slender square supports and spindle balustrade, glass and wood paneled door; first story right bay has a single double-hung window and left flanking entrance are a pair of double-hung windows; second story two sets of paired double-hung windows.
356	c.1891	90	Two and one-half story, frame Queen Anne style residence with cross-gable roof with front facing gable with bargeboard with kingpost, vine motif in bargeboard ends; shed roof full-width porch with rough-cut stone base, paired fluted Doric columns, spindle balustrade, double glass paneled door; first story tripartite double-hung window; second story has paired double-hung windows with entablature window head, with enlarged frieze area decorated with swag motif, windows flank panel decorated with arabesque motif tipped by broken pediment in low relief; gable has four double-hung windows flanked by engaged fluted Doric columns, sill with corbel stops, entablature with dentils under frieze, swag motif and stick styling in top of gable. Contributing one-story garage.
360	c.1909		Two and one-half story, frame residence with Colonial Revival style features; front facing gable roof; pedimented gable, shingled, tripartite double-hung windows with entablature window head; full-width flat roof porch has fluted Ionic columns, rough-cut stone base, spindle balustrade, upper porch with stick balustrade and canvas awning; first story glass paneled door with leaded sidelights with flanking tripartite window, single lights with leaded transoms; second story semi-hexagonal bay with double-windows, leaded-glass paneled porch door second story; end fluted Doric pilaster strips. Contributing one-story gabled roof garage.
362	c.1911		Two-story, frame "American Four Square" residence with hip roof with projecting eaves and modillions under eaves; hip roof dormer has a double-hung window and projecting eaves; full-width flat roof porch has Doric

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
362(cont'd)			columns with enlarged abacus, crowning cornice, stick balustrade, glass and wood paneled door with leaded sidelights, flanked on one side by a rectangular leaded window; first story tripartite window, single light; with leaded transoms; second story has two semi-hexagonal bays with double hung windows; end Doric pilaster strips.
366	c.1980		Two and one-half story, frame residence with front facing gable roof; pedimented gable has end brackets, tripartite double-hung window with diamond end tracery in top light, entablature window head with dentils under cornice; full-width hip roof porch, rough-cut stone base, glass and wood paneled door flanked on one side by a rectangular leaded window, right bay single-light window with leaded transom, wrought-iron supports and balustrade; second story has two semi-hexagonal bays with double-hung windows. Asphalt siding.
372	c.1911		Two and one-half story residence with Shingle style features; hip roof; full-width hip roof porch has Doric columns and shingled rail, projecting entrance has glass and wood paneled door; first story tripartite double hung window; second story semi-hexagonal bay with polygonal roof, center rectangular leaded window flanked by two double-hung windows; gabled dormer with flared eaves, bargeboard, round arched double-hung window with diamond tracery in top light. Contributing one-story flat roof garage.
378	c.1903		Two and one-half story, frame residence with front facing gable roof; pedimented gable, shingled, has brackets under projection, tripartite double-hung window with entablature surround with dentils under cornice; full-width hip roof porch has square Doric supports and stick, balustrade, projecting entrance has wood and glass paneled door; first story tripartite double-hung windows; second story semi-hexagonal bay has double-hung windows with a flanking left double-hung window. Contributing one-story garage.
384	c.1905		Two and one-half story, frame residence with Queen anne style features; front facing gable roof; pedimented gable, shingled, has brackets under cornice projection, tripartite double-hung windows with curvilinear design under sill, cornice window head with brackets; full-width hip roof porch with end pedimented gabled entrance, brackets under gable cornice, vine motif in tympanum, glass and wood paneled door flanked by double-hung windows, porch has a band of four double-hung windows; second bowed bay, center double-hung window with leaded sidelights; pilaster

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
384 (cont'd)			strip mullions, two double-hung windows. Contributing one-story gable roof garage.
388	c.1906		Two and one-half story, frame Colonial Revival style residence with hip roof with modillion blocks under eaves; hip roof dormer with projecting eaves and a pair of double-hung windows; partial-width hip roof porch has square Doric supports, stick balustrade and modillions under eaves, glass and paneled door with sidelights; first story single-light window with leaded transom; second story semi-hexagonal bay with double-hung center window with double-hung sides and paired double-hung windows on the right side; end Doric pilaster strips. Contributing one-story hip roof garage.
400	c.1909		Two-story, frame residence with hip roof with exposed rafter-tails under projecting eaves and curvilinear knee braces; hip roof dormers with exposed rafter-tails and curvilinear knee braces under eaves and a pair of double-hung windows; trellised entrance porch with square supports, wood paneled door with two light sidelights; first story boxed bay has a pair of double-hung windows, single double-hung light window; second story center double-hung window flanked by double-hung windows; full-width hip roof porch on north side, paired tapered square supports with column elaboration, stick balustrade, two double-sash, lighted, porch doors. Contributing one-story garage.
418	c.1909		Two-story, frame "American Four Square" residence with hip roof with brackets under projecting eaves; hip roof dormer with projecting eaves and has a pair of double-hung windows; full-width hip roof porch with glass paneled door; first story tripartite double-hung windows with leaded sidelights; second story semi-hexagonal bay with double-hung windows, flanking pair of double-hung windows. Contributing one-story garage.
422	c.1909		Two-story, frame "American Four Square" residence with hip roof with projecting eaves; hip roof dormer with projecting eaves and has a pair of double-hung windows; full-width gabled roof enclosed porch, tapered Doric pilaster strips, stick styling in gable, rough-cut stone base, three double-hung windows flank glass paneled door with transoms; second story has a set of paired double-hung windows.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
426	c.1910		Two-story, frame "American Four Square" residence with hip roof with modillion blocks under projecting eaves; hip roof dormer with modillion blocks under projecting eaves and has a pair of double-hung windows; full-width hip roof porch, enclosed, modillion blocks under projecting eaves, Doric end pilaster stripes with garland motifs, horizontal band of single lights with three-light transom, paneled apron, glass paneled door with transoms; second story boxed bay with a pair of double-hung windows and flanking single double-hung window. Contributing one-story garage.
428	c.1911		Two-story, frame "American Four Square" residence with hip roof with projecting eaves; hip roof dormer with projecting eaves and tripartite double-hung windows; full-width hip roof porch has rough-cut stone base, square tapered supports, glass and wood paneled door; first story four-part window single light with leaded transom; second story shingled, two sets of boxed bays with double-hung windows. Contributing one-story hip roof garage.
430	c.1910		Two and one-half story, frame residence with side gable roof; gabled through-the-cornice dormer with round-arched double-hung windows; full-porch partially enclosed has Doric square supports and pilaster strips, windows in porch are single-light with banded borders, glass paneled door; second story paired double-hung windows flank a center single double-hung window. Contributing one-story gable roof garage.
432	c.1898		Two and one-half story, frame residence with front facing gable roof; pedimented gable has brackets under cornice and three double-hung windows in gable; wood paneled door with lighted sidelights, bowed metal hood with flanking boxed bay with hip roof and tripartite window with four lights each with transom; second story two single double-hung windows with shutters; aluminum siding. Contributing one-story gable garage.
444	c.1914		Two-story, frame "American Four Square" residence with hip roof with modillion blocks under projecting eaves; hip roof dormer has projecting eaves, modillion blocks and three double-hung windows; full-width flat roof porch with tapered square supports with bracket capitals, stick balustrade on upper and lower porches, projecting entrance has three light beveled glass door with leaded sidelights; first story has tripartite window, single light with leaded transoms; second story has semi-hexagonal bay with double-hung window, lighted porch door. Contributing one-story hip roof garage.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Crescent Avenue, northwest side</u>			
448	c.1914		Two-story, frame "American Four Square" residence with hip roof with projecting eaves with corner braces; hip roof dormer with projecting eaves with exposed rafter-tails and three vertical light windows; full-width flat roof porch has square brick piers and shingled rail, three vertical light beveled glass door with leaded sidelights; first story tripartite window with single-light center with leaded transom and sidelights; second story semi-hexagonal bay with three vertical light over-one window, lighted double-sash porch door, wrought-iron supports and balustrade. Contributing one-story gable roof garage.
454	c.1895	91	Two and one-half story, frame residence with steep pitch side gable roof; large hip roof dormer has pair of double-hung windows with arched tracery full-width hip roof porch has pediment over stairs, square Doric supports with stick balustrade with center diamond-shape, wood and glass paneled door with flanking stained-glass rectangular window, left side of entrance are two double-hung windows; second story semi-hexagonal bay with double-hung windows and two flanking double-hung windows.
458	c.1906	91	Two and one-half story, frame Colonial Revival style residence with side gable roof with cornice end returns; two pedimented gable dormers with cornice end returns and round-arched windows with arched tracery in top light; pedimented entrance porch with arched tympanum, paired Doric columns and asterisk styled rail, lighted wood panel door; symmetrically placed square-headed double-hung windows on both stories with shutters.
464	c.1910	91	Two-story, frame "American Four Square" residence with hip roof with projecting eaves, exposed rafter-tails; hip roof dormer with projecting eaves, exposed rafter-tails and a pair of double-hung windows; full-width hip roof porch has exposed rafter-tails, paired stick supports with flared bracket capitals, glass paneled door; first story semi-hexagonal bay with double-hung windows; second story has a set of paired double-hung windows. Contributing one-story hip roof garage.
468	c.1915		Two-story, frame "American Four Square" residence with hip roof with projecting eaves, modillion blocks under eaves; hip roof dormer with projecting eaves, modillion blocks under eaves and three nine-light windows; partial-width deck roof porch with glass paneled door with leaded sidelight; two-story semi-hexagonal bay with double-hung windows; both porches have wrought-iron supports and balustrades; second story band course and twelve light double sash porch door.