

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
18	c.1904		Two-story, two-bay brick and shingle "Colonial Revival" style residence with pedimented gable roof with projecting eave with supporting brackets; pedimented center window with twelve/one lights flanked by nine/one windows; full-width front porch with brick pier supports with stick balustrade; second story stick balustrade; main entrance east side of facade; first floor square-headed one/one windows with stone lintel; second story bay window; glass paneled door leads to porch; two-story pedimented gable bay on west side. Contributing one-story frame garage, c. 1904.
22	c.1907		Two-story, two-bay frame and shingle "Colonial Revival" style residence with pedimented gable roof with extending eaves and front cornice with supporting brackets and Palladian window in pediment; full-width front porch with stone base, Doric column supports and spindle balustrade; glass paneled main entrance door with flanking elliptical window; first and second floor bay windows; upper porch stick balustrade; glass paneled door leading to porch. Fluted building end pilaster strips; two-story pedimented bay on north side. Contributing one-story frame garage, c. 1907.
26	c.1906	54	Two-story, two-bay frame and shingle "Colonial Revival" style residence with pedimented gable roof with extending eaves and front cornice with supporting brackets and Palladian window in pediment; full-width porch with stone base, Doric column supports with ancones above columns; glass paneled door with flanking elliptical window; first and second floor bay window; window and door surrounds with capping cornice; glass paneled door leading to porch; fluted building end pilaster strips; two-story pedimented bay on north side.
30	c.1906	54	Two-story, two-bay frame residence with pedimented gable roof with extending eaves and front cornice; tripartite one/one window in pediment; full-width front porch with stone base, square supports and stick balustrade; glass paneled main entrance with flanking stained-glass window; first floor tripartite one/one window; second floor bay window; multi-light door leading to porch; two-story pedimented bay on north side. Contributing one-story frame garage, c. 1906.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
32	c.1903	54	Two-story, two-bay frame residence with front-facing gable roof; false gable roof with stylized dentils; full-width enclosed front porch with five-sided bay and flat-top hip roof; paired flat-headed six/one windows; lighted main entrance flanked by Doric pilaster strips and ten-light sidelights; second floor tripartite six/one window; multi-light door leading to porch.
38	c.1905		Two-story frame residence with front-facing gable roof with bargeboard; semi-circular window in gable; shed roof through-the-cornice dormer on south side; full-width front porch with pediment over west end with square supports and entablature; wood paneled main entrance; tripartite one/one first floor window; four-part one/one second floor window. Contributing one-story frame garage, c. 1905.
42	c.1903		Two-story, two-bay frame "Colonial Revival" style residence with pedimented gable roof with flared eaves with eave brackets and dentils; Doric columns flank square-headed one/one gable windows; two second floor semi-hexagonal bay windows and Ionic fluted pilasters flanking second floor porch entrance; full-width porch with fluted Doric columns supporting entablature with glass paneled main entrance flanked by elliptical window; first floor tripartite one/one windows with plain surround; Ionic fluted building end pilasters; pedimented gable semi-hexagonal bay on south side. Contributing one-story frame garage, c. 1903.
48	c.1903		Two-story, two-bay frame vernacular "Queen Anne" style residence with hip roof with false gable; pedimented gabled semi-hexagonal second floor bay with one/one windows with fluted curved bracket corners; tripartite second floor one/one windows; full-width enclosed porch with bowed wing and single light windows with leaded transoms and entablature; pediment over glass paneled entrance with vine-leaf motif in tympanum; rough-cut regular course stone base.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
64	c.1906		Two-story, two-bay frame and shingle "Craftsman" style residence with gable roof with gabled dormers and projecting eave with triangular knee braces with rectangular gable window with diamond tracery; full-width porch with square supports, stick balustrade, four-part windows with diamond tracery and entablature with brackets under cornice; recessed wood and glass paneled main entrance.
70	c.1907		Two-story, two-bay frame and shingle "American Four Square" residence with hip roof with eave brackets; gabled dormer with bargeboard, eave rafter tails and stick styling; second floor boxed bay window with leaded top light and second floor semi-hexagonal eight/one bay window with six/one sidelights; full-width enclosed porch with paneled apron, bracketed cornice and wood paneled door with transom. Contributing one-story concrete garage, c. 1907.
72	c.1905		Two and one-half story, two-bay frame and shingle "Colonial Revival" style residence with front-facing gable roof with fish-scale shingles, Palladian window and projecting base with paired center brackets and end ancones; second floor pair of segmental arched bays with single light center window with Doric pilasters, leaded sidelights, paneled apron and transom; projecting elliptical glass paneled main entrance with flanking square leaded window with leaded transom; first floor tripartite single light windows with leaded transoms; half-fluted Ionic building end pilasters.
76	c.1905		Two-story, two-bay frame "Colonial Revival" style residence with hip roof and supporting ancones; front pedimented gable dormer with scroll and orb motif, flared dormer base and tripartite one/one window; second floor semi-hexagonal bay with square-headed one/one windows; second floor boxed bay round arch window with pedimented window head and supporting ancones; full-width enclosed porch with flanking engaged Doric columns, entablature with cornice and two/two windows with transoms; glass paneled main entrance with six rectangular lights with sidelights.
78	c.1886		Two-story, 'L'-shaped frame and shingle residence with hip roof rear wing and front-facing gable with recessed windows with diamond tracery; second floor one/one windows with shutters; first floor porch under rear wing with paired Doric columns.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
84	c.1894		Two-story, two-bay frame "Colonial Revival" style residence with pyramidal hip roof with cornice returns and pedimented gabled semi-hexagonal bay on south side; pedimented front dormer with supporting half-fluted Doric pilasters, round arched window, molding surround with keystone and top light tracery; second floor square-headed nine/one windows with shutters; full-width porch with Doric columns supporting entablature, stick balustrade and multi-light glass paneled main entrance with sidelights; Doric building end pilasters with first floor one/one windows with lintel window heads and shutters. Contributing one-story frame garage, c. 1894.
90	c.1905	55	Two-story, two-bay frame "Colonial Revival" style residence with hip roof and Terracotta chimney pots and dormer with supporting Doric pilasters, corner Doric pilasters and eight/one window; second floor twelve/one window with shutters; first floor multi-light window; full-width porch with square paneled Doric supports, spindle balustrade, entablature and wood paneled main entrance with leaded sidelights flanked by ten-light casement windows. Contributing one-story frame garage.
98	c.1903	55	Two and one-half story, two-bay frame "Queene Anne" style residence with front-facing gable roof with pedimented gable with supporting brackets and recessed one/one windows and round-arched blind window with semi-circular relieving shingled arch; three-story hip roof bay on north side with third floor porch with paired square supports; second floor rectangular window with diamond tracery; first and second floor one/one windows; partial-width enclosed porch with hip roof, fluted Doric supports, entablature, four-light window with three-light transom and glass paneled main entrance with paneled apron.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
100	c.1895	55	Two and one-half story frame, brick and stucco "Tudor" style residence with front-facing, steep-pitched gable roof with gabled dormers, barge-board with end brackets; projecting gable with decorative quaterfoil half-timbering and four twelve/one windows with pediment-shaped window head; second floor decorative half-timbering with two/one windows; first floor boxed bay window with paneled apron and single-light with leaded transom; partial-width porch with square supports with capital braces, stick balustrade, entablature and recessed main entrance. Contributing one-story frame garage, c. 1920.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
104	c.1895		Two and one-half story, three-bay frame "Colonial Revival" style residence with cross gable roof; pedimented front-facing gable with cornice end returns and paired straight-headed windows; full-width flat-roofed sun porch with dentils under extending eave, six-light door with transom; Doric pilaster strips flank three eight-light windows; second floor south end has five-sided bay with straight-headed windows and entablature; north boxed bay with tripartite window with entablature window head. Contributing one-story frame garage, c. 1920.
108	c.1911		Two and one-half story, two-bay frame and shingle "Craftsman" style residence with side gable roof with rafter tails and knee braces under extending eave; shed roof dormer with four square nine-light windows; shed roof full-width front porch with tapered square supports, rafter tails under eave and stick rail; four-light wood paneled door flanked by small rectangular leaded north bay window; tripartite first floor single-light window with leaded transom; second floor boxed bay with paired straight-headed windows.
112	c.1910		Two-story, two-bay brick and shingle "American Four Square" residence with hip roof with projecting eaves; three hip-roof dormers with small straight-headed windows; full-width hip roof sun porch with extending eaves, rough-cut regular course stone end piers; horizontal bands of five and three straight-headed windows flanking a wood and glass paneled door with arched span between porch supports; second floor paired tripartite windows with single-light transom. Contributing one-story concrete garage, c. 1910.
116	c.1909		Two and one-half story shingled "Craftsman" style residence with front-facing gable roof with bargeboard, flared eaves and curved end rafter tails; shed roof dormer with rafter tails under extending eaves and three straight-headed six/one windows; full-width hip roof front porch with rafter tails under extending eaves with square tapered supports with column elaboration, stick balustrade and horizontal band of ten-light windows; second floor paired straight-headed nine/one windows; north side entrance porch with hip roof with rafter tails, square supports with column elaboration and 'X'-style balustrade; glass paneled door with transom and sidelights. Contributing one-story frame garage, c. 1909.

Olms and Parks & Parkways Thematic Resources:

Parkside Subdivision (East) Historic District, Buffalo, Erie County, NY

Item 3 Page 246

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
128	c.1906		Two-story, three-bay frame and shingle "American Four Square" style residence with hip roof with extending eaves and rafter tails; three hip roof dormers with flared extending eaves and rafter tails; rectangular window; north recessed bay with four-light wood door; first and second floor straight-headed single-light window with transom; second floor elliptical stained-glass window with keystone.
130	c.1906		Two-story, two-bay frame "Colonial Revival" style residence with hip roof with flared eaves; three hip roof dormers with modillions under flared extending eaves and paired pilaster strips flanking straight-headed double-hung windows; full-width porch with Ionic fluted columns and spindle balustrade; south bay entrance with wood door flanked by one sidelight with eared architrave enframingent; first and second floor single-light windows with transoms, eared architrave enframingent, fluted Doric end building pilaster strips.
136	c.1908		Two and one-half story, two-bay frame "Colonial Revival" style residence with side gable roof with end returns and brackets under eave; two pedimented gable dormers with square-headed windows; full-width hip roof porch with square supports; south entrance bay with glass paneled door; first floor paired square-headed windows; two semi-hexagonal second floor bays with square-headed double-hung windows with entablature surrounds; building end pilaster strips; south side second floor oriel.
138	c.1907		Two and one-half story, three-bay shingled residence with Colonial Revival styling with pedimented gable roof with brackets under front projection and three straight-headed double-hung windows; full-width shed roof front porch with pediment over north end, corbel brackets under eave, vine motif in tympanum and square supports; south bay glass paneled door flanked by small rectangular window; first floor square-headed windows; second floor semi-hexagonal bay with straight-headed double-hung windows; shed roof oriel on south side of building.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
142	c.1906		Two-story, two-bay frame residence with Colonial Revival styling with hip roof with brackets under eave; three hip roof dormers with brackets under eaves and straight-headed double-hung windows with arched tracer in top light; full-width shed roof front porch with wrought-iron supports and shingle and spindle rail; south end entrance with glass paneled door flanked on one side by square leaded window; single-light first floor window with transom; two second floor semi-hexagonal bays with square-headed double-hung windows with entablature surrounds; residence sided.
144	c.1908		Two-story, two-bay shingle "American Four Square" residence with hip roof; three hip roof dormers with two square-headed double-hung windows; partial-width hip roof enclosed entrance porch with end piers, multi-light double-sash doors with transom flanked by multi-light windows with transoms; first floor straight-headed nine/one windows; second floor boxed bay with tripartite window; paired straight-headed south bay windows.
146	c.1907		Two and one-half story, two-bay frame residence with Craftsman and Prairie School styling with side gable roof with curved brackets under eave; gabled dormers with bargeboard and straight-headed double-hung windows; full-width sun porch with brick end piers and end brackets under roof eave; horizontal band of paired single-light windows with twelve-light transom; second floor paired straight-headed nine/one windows.
150	c.1908	56	Two-story, two-bay frame "American Four Square" residence with hip roof; hip roof dormer with two straight-headed double-hung windows; partial-width hip roof entrance porch with end piers; center entrance with glass paneled door with three-light transom flanked by three-light windows with transom and paneled apron; tripartite first floor straight-headed one/one windows; second floor boxed bay with straight-headed windows with diamond tracery in top light; paired straight-headed six/one south bay windows.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
154	c.1905	56	Two and one-half story, three-bay shingle "Queen Anne" style residence with side gable roof with Palladian windows in gable ends; pedimented gable dormer with paired straight-headed one/one windows; partial-width front porch with wrought-iron support and stick balustrade; glass paneled door with leaded sidelights and transom; multi-light second floor door leading to porch; second floor square-headed one/one window; two and one-half story south bay tower with conical roof with saw-tooth shingle band on second floor and straight-headed double-hung windows. Contributing one-story frame garage, c. 1905.
160	c.1907	56	Two and one-half story, three-bay frame and shingle "Colonial Revival" style residence with front-facing gable roof with dentils in raking cornice and Palladian window in gable; gabled side dormers with quarter round windows flanking the chimney; partial-width flat-roof front porch with rough-cut regular course stone base and pedestals; fluted Ionic columns supporting entablature with dentils under cornice; center entrance with glass paneled door with sidelights; pilaster strips flank entrance and support entablature door head with denticulated cornice; tripartite first floor straight-headed window with single-light center, transom and double-hung sides; south end bowed bay with straight-headed one/one windows; second floor end bowed bays with straight-headed one/one windows; paired elliptical center bay windows with entablature window head with garland motif in frieze; fluted Doric building end pilaster strips. Contributing two-story frame garage, c. 1907.
164	c.1905		Two and one-half story frame and shingle residence with cross gable roof and 'L'-shaped plan; first floor hip roof bay with straight-headed one/one windows; second floor overhang; two second floor straight-headed one/one windows with louvered shutters; south side oriel; recessed south wing with glass paneled door with fluted pilaster strips and broken pediment door head. Contributing one-story frame garage, c. 1905.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
170	c.1905		Two-story, two-bay frame "Colonial Revival" style residence with hip roof; three hip roof dormers with straight-headed double-hung windows with flanking pilaster strips; north bay projecting entrance with wood paneled door and eared architrave surround; first floor straight-headed one/one window with eared architrave surround and shutters; two second floor semi-hexagonal bays with straight-headed one/one windows; building proper has entablature with triglyphs decorating frieze; fluted Doric building end pilaster strips. Contributing one-story frame garage, c. 1905.
172	c.1905		Two-story, two-bay frame "Colonial Revival" style residence with hip roof; three hip roof dormers with three straight-headed windows with arched tracery in top light; full-width hip roof front porch with fluted Ionic columns supporting entablature with ancone brackets and spindle balustrade; south entrance bay with wood paneled door flanked on one side by small straight-headed window with leaded transom; first floor square-headed one/one window; two second floor semi-hexagonal bays with straight-headed one/one windows; fluted Doric end pilaster strips; second floor south side boxed bay.
176	c.1905		Two-story, two-bay frame "Colonial Revival" style residence with hip roof; three hip roof dormers with straight-headed one/one windows; south entrance bay with wood paneled door with louvered shutters flanked by a small straight-headed window; two first floor ten/ten windows; second floor oriel with straight-headed one/one windows with entablature surround; single straight-headed window with louvered shutters. Contributing one-story frame garage, c. 1905.
180	c.1904		Two and one-half story, two-bay frame and shingle residence with Colonial Revival styling with steep-pitched pedimented gable roof with tripartite straight-headed window flanked by pilaster strips supporting entablature window heads with ancone brackets; full-width hip roof front porch with south bay entrance with wood paneled door flanked by one sidelight; four-part casement window; two semi-hexagonal second floor bays with straight-headed windows with plain surround. Non-contributing one-story frame garage.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
184	c.1907		Two and one-half story, two-bay frame and shingle "Craftsman" style residence with side gable roof with curved volute brackets; two gabled dormers with bargeboard, rafter tails and straight-headed six/one windows with entablature surround; south bay boxed entrance with three-light wood door flanked on one side by a small straight-headed six/one window with molded surround; first floor multi-light window with surround; paired straight-headed one/one second floor windows with entablature surround; pair of south side boxed bay windows with shed roof; second floor triangular oriel. Contributing one-story concrete block garage, c. 1907.
198	c.1911		Two-story, three-bay stucco and shingle "Craftsman" style residence with side gable roof with bargeboard, rafter tails and triangular knee braces under eave; shingled first floor with shed roof visor hood with exposed rafter tails spanning first floor; center bay hip roof entrance porch with horizontal band of single-light windows; vertical three-light glass paneled door; east side shed roof porch with end pier supports; second floor straight-headed nine/one windows with entablature surrounds; band course. Contributing one-story frame garage, c. 1911.
200	c.1904		Two and one-half story, three-bay frame "Colonial Revival" style residence with side gable roof with modillion brackets under eave; pedimented gable dormer with three straight-headed six/one windows; south bay partial-width gable porch with square supports and stick balustrade; glass paneled door with four-light transom; semi-hexagonal bay window with straight-headed nine/one windows with entablature window head; second floor straight-headed nine/one windows with entablature window head with louvered shutters. Contributing one-story frame garage, c. 1904.
202	c.1910		Two and one-half story, two-bay frame and shingle residence with pedimented gable roof with front projecting cornice and three-part straight-headed six/one windows; full-width flat roof front porch with rough-cut irregular course stone base with rough-cut stone supports; partial-width upper porch with stick balustrade; north bay boxed entrance with glass paneled door flanked by square leaded window; first and second floor paired and boxed straight-headed six/one windows; second floor boxed bay with single straight-headed six/one windows; south side two-story boxed bay with pedimented gable.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
206	c.1908		Two and one-half story, two-bay shingle residence with Colonial Revival styling with pedimented gable roof; modillion brackets under front projecting cornice and three-part one/one window; full-width flat roof front porch with Ionic columns and curved baluster balustrade; north entrance bay with glass paneled door; first floor tripartite straight-headed one/one window; second floor semi-hexagonal bay with straight-headed one/one windows; second floor porch with glass paneled door, with entablature window and door heads; two-story south side semi-hexagonal bay with pedimented gable.
208	c.1908	57	Two and one-half story, two-bay frame and shingle residence with Colonial Revival styling with pedimented gable roof with front projecting cornice; recessed paired straight-headed one/one windows with lintel window head; full-width flat roof front porch with square Doric supports with brackets under cornice and spindle balustrade; south end boxed entrance with glass paneled door; first floor straight-headed single-light window with transom; second floor semi-hexagonal bay with straight-headed one/one window; second floor porch with glass paneled door; south side two-story semi-hexagonal bay with pedimented gable.
214	c.1923	57	Two-story, three-bay brick "American Four Square" style residence with hip roof with extending eaves with exposed rafter tails; three hip roof dormers with rafter tails under flared extending eaves and paired six/one windows; partial-width flat roof sun porch with horizontal band of paired windows with four-light transom; upper porch paneled rail; first floor straight-headed six/one windows with relieving arch; second floor porch with multi-light door and end bay straight-headed eight/one windows; south side entrance with metal entrance hood with ornamental glass border. Contributing one-story brick garage, c. 1923.
218	c.1909	57	Two-story, two-bay frame "Colonial Revival" style residence with steep-pitched hip roof with modillion brackets under extending eaves; hip roof dormer with two straight-headed windows with top light tracery; full-width flat roof porch with Doric columns and spindle balustrade; south end entrance with glass paneled door flanked on one side by small rectangular window; tripartite first floor window with top light tracery; second floor semi-hexagonal bay with straight-headed double-hung window with arched tracery in top light; south bay paired straight-headed windows with arched tracery in top light and plain window surround; north side hip roof boxed bay.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
222	c.1909		Two-story, two-bay frame and shingle "American Four Square" residence with hip roof with projecting eaves; hip roof dormer with projecting eaves with paired straight-headed windows with diamond tracery in top light; south bay hip roof partial-width enclosed porch with center entrance flanked by paired single-light windows with transom; first floor single-light window with transom; second floor paired straight-headed one/one windows. Contributing one-story frame garage, c. 1909.
226	c.1908		Two and one-half story, two-bay frame and shingle "Craftsman" style residence with side gable roof with knee braces under eave; gabled dormer with bargeboard and tripartite straight-headed double-hung window with tracery in top light; south bay partial-width gabled porch with bargeboard, wrought-iron supports and stick styling in gable; six-light wood door flanked on one side by small straight-headed double-hung window; first floor paired full-length windows with two-light transoms; second floor paired straight-headed windows with diamond tracery in top light.
228	c.1924		Two-story, two-bay shingle "American Four Square" residence with hip roof; hip roof dormers with two six-light windows; full-width front porch with square supports; first and second floor tripartite windows; second floor porch with wood paneled door; south side entrance with wood and glass paneled door and pilaster strips supporting the entablature with crowning cornice; shallow upper porch wrought-iron balconet. Non-contributing one-story frame garage.
272	c.1911		Two and one-half story, two-bay shingle and stucco "Craftsman" style residence with side gable roof with paired knee braces under eave; shed roof dormer with exposed rafter tails under extending eave with four-part nine-light windows; full-width hip roof porch with stucco end piers and rail, curved between porch supports; south entrance with eight-light wood paneled door flanked on one side by rectangular leaded window; first floor four-part single-light window with transom; second story band course; second floor boxed bays with paired straight-headed six/six windows; entablature surround with capping cornice; south side second floor gabled bay.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
276	c.1909		Two-story, two-bay brick and shingle "American Four Square" style residence with hip roof with dentils under eave; hip roof dormer with two twelve-light windows with denticulated eaves; north bay partial-width front porch with round-arched openings with relieving arch; eight-light wood paneled door flanked on one side by small square window with diamond tracery; first floor four-part single-light window with twelve-light transom and relieving arch; second floor boxed south bay with two twelve/one windows with entablature surround; second floor south side triangular shaped oriel.
280	c.1908		Two-story, two-bay frame and shingle residence with Craftsman and Colonial Revival styling and hip roof; semi-circular pedimented dormer with Doric engaged columns flanking tripartite window; second floor paired straight-headed double-hung windows; full-width porch with gabled projection with bargeboard decorated with square motif and tapered square supports with brace brackets at capitals; south bay entrance with multi-light door flanked by tripartite double-hung windows with transom; first floor corner fluted Doric pilaster strips; south side triangular shaped oriel. Contributing one-story frame garage, c. 1908.
284	c.1909		Two and one-half story, two-bay frame "Craftsman" style residence with side gable roof with exposed rafter tails and knee braces under eave; gabled dormer with two square-headed double-hung windows; second floor paired straight-headed twelve/one windows with louvered shutters; full-width shed roof porch with square Doric supports and rough-cut regular course stone base; north entrance bay with six-light wood paneled door flanked on one side by straight-headed multi-light windows; tripartite first floor multi-light window. Non-contributing one-story frame garage.
286	c.1912		Two and one-half story, two-bay frame and shingle residence with Colonial Revival styling with steep-pitched pedimented gable roof with front projecting cornice with modillion brackets, four-part straight-headed double-hung window with arched tracery in top light and entablature surround; north bay second floor porch with glass paneled door with surround; two tripartite windows with entablature and surround; full-width front porch with tapered square supports with modillion blocks under eave and paneled rail; north entrance bay with glass paneled door with sidelights; first floor tripartite single-light window.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
290	c.1905		Two-story, three-bay frame residence with Colonial Revival styling with hip roof; three pedimented gable dormers with end returns with modillions under raking cornice, leaf and vine motif in tympanum and two straight-headed windows with arched tracery in top light; second floor semi-hexagonal north bay; bowed south bay; center bay multi-light door leading to second floor porch; two-story north and south side semi-hexagonal bay with pedimented gable; full-width partially enclosed porch with modillions under eave and horizontal band of five straight-headed nine/one windows; recessed north bay entrance with paneled corner support and wood paneled entrance with sidelights. Contributing one-story frame garage, c. 1905.
294	c.1905		Two and one-half story, two-bay frame and shingle residence with Colonial Revival styling with steep-pitched pedimented gable roof with projecting front cornice with brackets and two straight-headed one/one windows with spindle mullion; first and second floor straight-headed one/one windows; south side two-story semi-hexagonal bay with pedimented gable; second floor semi-hexagonal south bay; first floor full-width shed roof porch with pediment over north end with leaf pattern in tympanum, square Doric support with Vitruvian scrollfrieze motif and glass and wood paneled door flanked on one side by small leaded-glass window.
298	c.1909	58	Two and one-half story, two-bay frame and shingle "Colonial Revival" style residence with steep-pitched cross gable roof with front projecting cornice and Palladian window; second floor semi-hexagonal bay with straight-headed double-hung windows; second floor north bay porch with multi-light door flanked by straight-headed six/one window; full-width flat roof partially enclosed front porch with rough-cut regular course stone base and pedestals, fluted Doric columns and horizontal band of straight-headed single-light windows with three-light transom; north recessed entrance with wood paneled door flanked by sidelights. Contributing two-story frame carriage house, c. 1909.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
304	c.1891	58	Two and one-half story frame and shingle "Queen Anne" style residence with hip roof with steep-pitched pedimented gable bay with brackets under front eave; tripartite gable window with diamond tracery, false pediment and dentils; three-story semi-hexagonal bay with polygonal tent roof on one side; first and second floor one/one windows; north bay entrance with wood paneled door with entablature surround with dentils under cornice and leaded windows flanking entrance on one side. Non-contributing one-story frame garage.
305	c.1912	58	Two-story, two-bay frame and shingle "American Four Square" residence with hip roof with projecting eaves with brackets; hip roof dormer with tripartite window with rafter tails under extending eave; second floor semi-hexagonal bays with straight-headed six/one windows; tripartite first floor single-light window with leaded transom; south boxed entrance bay flanked by engaged piers; full-width front porch with square Doric supports with column elaboration and stick balustrade.
310	c.1889		Two and one-half story, three-bay frame and shingle "Queen Anne" style residence with side gable roof with modillion blocks under eave; hip roof dormer with paired square windows with tracery border; second floor straight-headed one/one windows with flanking pilasters with curved capital and base; two-story semi-hexagonal tower with polygonal tent roof; first and second floor straight-headed windows with rectangular windows in roof base; first floor straight-headed one/one window with entablature surround and louvered shutters; center bay entrance with glass and wood paneled door with entablature window surround.
316	c.1896		Two and one-half story, two-bay frame and shingle "Colonial Revival" style residence with steep-pitched pedimented gable roof with front-facing cornice with brackets and tripartite straight-headed sixteen/one windows; second floor semi-hexagonal north bay with straight-headed one/one windows; two-story south side semi-hexagonal gable bay; full-width shed roof front porch with pediment over south end with fluted Doric columns; north boxed entrance bay with glass and wood paneled door flanked by small double-hung window; first floor single-light window with leaded transom.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
322	c.1891		Two and one-half story, two-bay frame "Queen Anne" style residence with steep-pitched pedimented gable roof with two straight-headed one/one windows with brackets under cornice window head; north and south side hip roof dormers; two-story south end semi-hexagonal tower with hip roof and straight-headed one/one windows; partial-width gabled front porch with wrought-iron supports and glass and wood paneled door flanked on one side by straight-headed one/one window; residence sided. Non-contributing one-story frame garage.
324-326	c.1910		Two and one-half story, two-bay frame and shingle residence with cross gable roof with shingled front cornice with brackets and four-part six/one window with brackets under cornice head; second floor end bay with tripartite straight-headed six/one windows; full-width one-story hip roof front wing with two tripartite windows; south side entrance with multi-light door with four-light transom flanked by semi-hexagonal hip roof bay. Non-contributing one-story frame garage.
332	c.1905		Two and one-half story, two-bay frame and shingle "Colonial Revival" style residence with pedimented gable roof with front projecting cornice with brackets and Palladian window; pedimented gable dormers on north and south sides; second floor semi-hexagonal north bay with straight-headed one/one windows; full-width front porch with square Doric supports with stick balustrade; south end bay glass paneled door; first floor tripartite window.
336	c.1901		Two and one-half story, three-bay frame "Colonial Revival" style residence with pedimented gable roof with brackets under projecting cornice and Palladian window; pedimented gable dormers on north and south sides; second floor semi-hexagonal north bay with multi-light porch door flanked by straight-headed one/one windows; full-width front porch with square support and stick style balustrade; south end glass paneled entrance; tripartite first floor window; residence sided.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
338	c.1904		Two-story, three-bay frame "Colonial Revival" style residence with hip roof with brackets under extending eave; six pedimented dormers with straight-headed one/one windows; second floor semi-hexagonal north bay with straight-headed windows; second floor south bay porch with glass paneled door and stick balustrade; first floor full-width front porch with square Doric supports with dentils under cornice and horizontal stick balustrade; recessed north bay entrance with glass paneled door; south end bay entrance with wood paneled door; tripartite first floor window; Doric building end pilaster strips.
342	c.1905		Two-story, two-bay frame "American Four Square" residence with hip roof with brackets under extending eave; three hip roof dormers with three straight-headed one/one windows; second floor semi-hexagonal north bay with straight-headed windows; second floor south bay porch with glass paneled door; first floor full-width sun porch with south end bay entrance with glass and wood paneled door flanked by sidelights with transom; horizontal band of five straight-headed double-hung windows with transom; Doric building end pilaster strips; residence sided.
344	c.1904		Two-story, three-bay frame "Colonial Revival" style residence with hip roof with projecting eave with brackets; five hip roof dormers with dentils under roof eave and paired straight-headed one/one windows; second floor semi-hexagonal north bay with straight-headed windows; second floor porch with multi-light door; first floor full-width front porch with square Doric supports and spindle balustrade; south end entrance bay with glass paneled door; tripartite first floor window; north recessed entrance bay with glass paneled door; fluted Doric end pilaster strips.
356	c.1913		Two and one-half story, two-bay stucco residence with pedimented gable roof with cornice returns, modillions under raking cornice and tripartite single-light window; second floor end bay with small six-light window; first and second floor porches with multi-light doors with flanking multi-light windows; partial-width front porch with square end piers and stick balustrade; north end entrance bay with multi-light door with pediment door head with cornice returns.

արթեզ լիւրէյ անդ մօօզ Կսւրէզզ զօօր մէք լօռւ-լիցիւ Զիգէլիցիւ: Պօս-
ւրէլլիսէզ Եւրիսու Խօւրի մէք լիւրէզ ըօլիւ Կօլլիսս ԶնԽօւլլիւց Կզիւսու
Խսզզ Ելիցիւ\օս Խիւզօս մէք լօսլւրէզ Զիլլիւ: Էլլիւ էլօօր Զօլլի Զլ
Կիլլիսլ: Զէօսլ էլօօր Զսլ Կօլլիս: Էլլիւ անդ Զէօսլ էլօօր Զիւրիցիւ-
Զիլլիւց մէք Խլիւսիզլ լիւ Լօօլ մէք Խլօլէօլլիւց ըօլէզ Եսլէ անդ Կօլլիւ
Լւօ-Զօլլ, Լւօ-Զլ Զիլլիցիւ Լէզիզսու մէք Լիւլլիսս անդ Խիւրից Զիլլիւ

ՀԻՆՅԻՐԲ-ՔԵՐԳԵՍ ՕՍԵ\ՕՍԵ ՄԻՊՈՄ՝ յՈՒ-ՏՈՒՐԱՅԻՐՈՒՄՈՒՆ ՕՍԵ-ՏՐՈՒՆ ԷՆՏԵ ՑԻՆԳԵ՝
ԶԻՅԵՑ ԽԱՍԵՐԵՍ ՊՈՐԻ ՄԻՐ ԷՆՏԻՄՈՒՆ ԼԵՏԻՎԱՅԻՐԱՅ ԵՐԳԵՍ ՄԻՊՈՄ՝ ԷՆՏԵ ԷՋՈՐ
ՈՐԻՏ ՏՈՒՄԱՅ՝ ՉԻՄՈՒՅ ԲԱՅԵՐԳԵ ՑԱՍ ՍՈՒՐ ԲՈՒՐԵՍ ԵՐԵՐԱՅԵՑ ԲԱՆ ՄԻՐ
ՑԱՐՈՍԱՅ՝ ԷՆՏԻ-ՄԻՐԻ ԷՐԱՐ ԽՈՒՐ ՄԻՐ ԵՐԵՐԱՅԻՄՈՒՆ ԵՐԵՑ ՄԻՐ ԲԻՐՔԵՐԵՑ՝
ԶՈՒՅ ԲԱՆ ՄԻՐ ՉԻՆՅԻՐԲ-ՔԵՐԳԵՍ ՊՈՒՐԵ-ՄԱՅ ՄԻՊՈՄՈՒՆ ՄԻՐ ԵՐԵՐԱՅԻՐԱՅ
ԷՐԵՑ ՉԻՆՅԻՐԲ-ՔԵՐԳԵՍ ՊՈՒՐԵ-ՄԱՅ ՄԻՊՈՄՈՒՆ՝ ԷՐՈ ՉԵՐԱՅ ԷՋՈՐ ՉԵՐԱ-
ՄԻՐ ԼՈՒՐ ՄԻՐ ԵՐԵՐԱՅԻՄՈՒՆ ԵՐԵՑ ՄԻՐ ԲԻՐՔԵՐԵՑ՝ ԷՐԵՑ ՄԻՐ ԼՈՒՐ ՊՈՒՄԵՐՆ ՄԻՐ
ԷՐՈ-ՏՐՈՒՆ՝ ԷՐՈ-ԲԱՆ ԷՆՏԵ ԼԵՏԻՎԱՅԵՑ ՄԻՐ ՏՈՒՄԱՅ ԵՐԱՅԱՅ ՉԷՆՏԻՄՈՒՆ ՄԻՐ

[illegible]

մօօգ ԲՆԱԵՂԵՂ զօՐԷ՝ ՇՈՒՄԻՐՈՒՄԻՆՍ ՕՆԵ-ՏՐՈՒՆ ԷՐԱՄԵ ՑԱԻՑԵՑ՝ Ը՝ ԴԺԴՕ՝
 ՏՆԻԲՈՒՐՏ՝ ՏԻՐԿ ԲՅԱՆՏԷՐԱԳԵ ՏՈՂ ՆՈՒՐԻ ՆՈՂ ՆԱՐԱՆՍԵ ԲՅԱՆՄԻՐ ԶԻՅԱՏ ՏՈՂ
 ԴԵՐԳԵՂ ԸՆԴՍՈՄ՝ ԷՐԱՐ ԷՐՈՐ ԷՐԴԴ-ՄԻՂԻՐ ԷՐՈՒՐ ԲՈՒՐԻ ՄԻՐԻ ՇԴՆԱԵ ԴՈՒՐԸ
 զօՐԷ՝ ԷՐԱՐ ԷՐՈՐ ՇԵՄԻ-ՄԵՐՑՈՒՄՅԱՅ ԲՅԱՆՄԻՐ ՏԻՆԻՂԵ-ԴԻՑԻՐ ՄԻՆՈՄՑ ՄԻՐԻ
 ՄԱՍԻՆ ՄԻՆՈՄ՝ ՇԵՐՈՂ ԷՐՈՐ ԲՈՒՐԻ ՄԻՐԻ ՆՈՒՐԻ ԲՅԱՆ ՂՈՒՐԵ-ՏԱՅՐ ՄՈՒՐԴԻ-ԴԻՑԻՐ
 ՄԻՆՈՄՑ՝ ՇԵՐՈՂ ԷՐՈՐ ՇԵՄԻ-ՄԵՐՑՈՒՄՅԱՅ ԲՅԱՆՄԻՐ ՏԸՆԴԻՑԻՐ-ՄԵՐԳԵՂ ՂՈՒՐԵ-
 ՄԻՐԻ ԵՐԸՆՈՒՄԻՆՍ ԵՐԱՆ ՄԻՐԻ ՄԻՐԿԵՐՏ ՏՈՂ ԸՐԵՆ ՏԸՆԴԻՑԻՐ-ՄԵՐԳԵՂ ՆԻՆԵՍՈՆ
 ՂԵՐՍԵ ՄԻՐԻ ՄԻՐ ԼՈՒՔ ՄԻՐԻ ԲՈՒՐՏԸՐՈՒՄԻՆՍ ԵՐԱՆ ՄԻՐԻ ՄԻՐԿԵՐՏ՝ ՄԻՐ ԼՈՒՔ ՂՈՒՄԵՐ
 ԴՄՈ-ՏՐՈՒՆ՝ ԸՄՈ-ԲՅԱՆ ԷՐԱՄԵ ՏՈՂ ՏԻՆԻՂԵ "ՎՄԵՐԻՏԱՆ ԸՈՒ ՇԴՆԱԵ" ՏԸՆԵ ԼԵՅԻ-

DESCRIPTION

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
374	c.1907		Two and one-half story, two-bay frame and shingle "Colonial Revival" style residence with pedimented gable roof with front projecting cornice with brackets and bowed bay window with straight-headed one/one windows with entablature window head; full-width front porch with rough-cut regular course stone base, square Doric supports, stick balustrade and north entrance bay with glass paneled door flanked by oval with surround and keystone; second floor semi-hexagonal south bay with straight-headed windows; second floor porch with multi-light door, entablature window and door surround; south side pedimented gable bay; tripartite first floor window.
378	c.1906		Two and one-half story, three-bay frame "Colonial Revival" style residence with side gable roof; pedimented gable dormers with cornice returns and round arched windows with tracery in top light; second floor semi-hexagonal south bay with straight-headed one/one windows; second floor porch with multi-light door; first floor partial-width front sun porch with horizontal band of five straight-headed six/one windows with transom; north end entrance porch with square Doric corner support and glass and wood paneled door. Contributing one-story concrete block garage, c. 1920.
380	c.1913		Two and one-half story, two-bay frame and shingle residence with Colonial Revival styling with pedimented gable roof with cornice end returns with ancone supports and tripartite straight-headed window; second floor porch with multi-light door; second floor semi-hexagonal bay with straight-headed double-hung windows; first floor full-width front porch with square Doric supports, stick balustrade and north end entrance bay with glass paneled door with sidelights; tripartite first floor straight-headed double-hung windows.
384	c.1913		Two and one-half story, two-bay shingle and stucco "American Four Square" residence with gable on hip roof with projecting eaves and tripartite gable window; second floor windows with louvered shutters; two-story south side clipped gable bay with first floor entrance; full-width first floor sun room with hip roof with wide projecting eaves, two tripartite straight-headed double-hung windows and two straight-headed single-light windows with transom. Non-contributing one-story frame garage.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
392	c.1905		Two-story, three-bay frame "Colonial Revival" style residence with hip roof with extending eaves; pedimented gable front dormer with Palladian window; gable side dormers with straight-headed double-hung window; second floor semi-hexagonal north bay with straight-headed windows; two-story semi-hexagonal south bay with straight-headed one/one windows; center bay entrance with two-light wood paneled doors with pediment door head and fluted Doric pilaster strips flanked on one side by a straight-headed one/one window; residence sided. Non-contributing one-story frame garage.
396	c.1913	59	Two-story, three-bay frame and shingle "American Four Square" style residence with hip roof with projecting eaves; hip roof dormer with exposed rafter tails under extending eaves and tripartite straight-headed one/one windows; second floor end bay straight-headed ten/one windows with eight/one center bay window; partial-width front porch with massive square end piers; stick balustrade and center entrance bay with three-light wood door; first floor tripartite window; residence sided.
402	c.1905	59	Two-story, three-bay frame "Colonial Revival" style residence with hip roof with dentils under eave; pedimented gable dormers with straight-headed six/six windows; second floor straight-headed six/six windows with louvered shutters; two-story Doric pilasters flanking bays; first floor semi-hexagonal end bays with straight-headed windows with transoms; center entrance bay with wood paneled doors and leaded sidelights; residence sided. Contributing stone and cement garage, c. 1905.
406	c.1914	59	Two-story, two-bay shingle "American Four Square" style residence with hip roof with projecting eaves with exposed rafter tails; hip roof dormers with extending eaves with exposed rafter tails and tripartite straight-headed windows; first and second floor straight-headed eight/one windows with louvered shutters; partial-width gable porch with Doric columns and decorative cut-out rail; south bay shed roof entrance hood with two glass paneled doors. Contributing one-story frame garage, c. 1914.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
410	c.1914		Two-story, two-bay frame and shingle "American Four Square" style residence with hip roof with projecting eaves with modillion brackets; hip roof dormer with extending eave with brackets and three nine-light windows; first and second floor tripartite straight-headed nine/one windows; second floor porch with double-sash multi-light door; first floor full-width front porch with eave brackets, square Doric supports and stick rail; south end bay entrance with multi-light door with sidelights. Non-contributing one-story frame garage.
412-414	c.1920		Two and one-half story, two-bay frame and shingle residence with Colonial Revival styling with pedimented gable roof with front projecting cornice and tripartite straight-headed three/one window with cornice window head; north and south side shed roof dormers; second floor semi-hexagonal bay with single-light windows; second floor porch with north bay double-sash multi-light doors; first floor full-width front porch with extending eaves and wrought-iron supports; north end entrance bay with multi-light door with sidelights; first floor tripartite single-light window. Non-contributing one-story frame garage.
416	c.1910		Two and one-half story, two-bay frame and shingle residence with Colonial Revival styling with cross gable roof with front projecting cornice with three straight-headed one/one windows with cornice window head; second floor bowed bays with straight-headed windows; first floor partial-width front porch with wrought-iron supports and south end bay entrance with wood paneled door; first floor paired straight-headed one/one windows; first floor north side boxed and semi-hexagonal bays; building end fluted Doric pilaster strips. Contributing one-story stone garage, c. 1910.
426	c.1909		Two-story, two-bay shingled residence with hip roof with extending eave with rafter tails; north and south side hip roof dormers; second floor porch with double-sash doors and paired straight-headed six/one windows; three-story south side gabled bay with two-story round arched window; first floor full-width hip roof front porch with Doric columns, end piers and decorative cut-out rail; first floor glass paneled entrance door with flanking pilaster strips and supporting entablature. Contributing one-story frame garage, c. 1909.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
432	c.1892		Two and one-half story, two-bay frame and shingle "Colonial Revival" style residence with side gable roof with cornice end returns; steep-pitched pedimented gable dormer with cornice end returns with paired brackets and recessed Palladian window with round arch and keystone; two-story semi-hexagonal south bay with straight-headed windows; second floor north bowed bay with straight-headed one/one windows; first floor north bay entrance with glass paneled door flanked on one side by single-light casement window; center bay elliptical window with keystone.
438	c.1890	60	Two and one-half story, three-bay frame and shingle "Queen Anne" style residence with side gable roof; second floor semi-hexagonal pedimented gable bay with end bracket supports and straight-headed double-hung windows and gable with two one/one windows; second floor south end polygonal bay with flared tent roof and straight-headed one/one windows; first floor full-width front sun porch with center entrance with double glass paneled doors with sidelights, curved brackets under roof eave at entrance and pilaster strips flanking single-light windows with paneled aprons.
442	c.1910	60	Two-story, two-bay frame "American Four Square" style residence with hip roof with extending front eave; hip roof dormer with three straight-headed double-hung windows; two second floor bowed bays with straight-headed one/one windows; first floor full-width front porch with tapered square Doric supports, paneled rail and extending eaves; south entrance bay with glass paneled door with sidelights flanked on one side by a small square leaded window; first floor tripartite single-light window with transom; paneled building end pilaster strips.
444	c.1901	60	Two-story, three-bay frame residence with Colonial Revival styling with hip roof with eave brackets; three pedimented gable dormers with paired straight-headed windows; second floor bays with straight-headed one/one windows with louvered shutters with cut-out pattern; first floor partial-width sun porch with paired eight-light windows with pilaster strips flanking bays; north entrance bay with pedimented entrance surround with wood paneled door flanked by eight-light sidelights.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
452	c.1903		Two and one-half story, two-bay frame and shingle residence with steep-pitched pedimented gable with front projecting cornice with brackets with end ancones and Palladian gable window; second floor semi-hexagonal bay with straight-headed double-hung windows; second floor porch with north bay double-sash multi-light doors; south side pedimented gable bay; first floor full-width front porch with partial-width sun porch with brick end piers flanking four straight-headed windows; recessed north entrance bay with corner brick pier support and glass paneled door; residence sided. Non-contributing one-story frame garage.
456	c.1913		Two and one-half story, two-bay frame and shingle residence with cross gable roof with front projecting cornice and tripartite gable window with cornice window head; second floor semi-hexagonal bay with straight-headed one/one windows; second floor porch with north bay glass and wood paneled door; first floor full-width front porch with roof eave brackets and square Doric supports; north entrance bay glass paneled door flanked by leaded glass window; first floor tripartite straight-headed nine/nine window. Contributing one-story frame garage, c. 1913.
462-464	c.1899		Two and one-half story, three-bay frame "Colonial Revival" style residence with hip roof; hip roof dormers with paired straight-headed one/one windows; second floor semi-hexagonal end bays with pedimented gables and straight-headed one/one windows; fluted Ionic pilaster strips flanking bays; first floor full-width front porch with pediment over center bay, Doric columns and double glass paneled doors; first floor end bay tripartite windows. Contributing one-story frame garage, c. 1899.
466	c.1905		Two-story, two-bay frame "American Four Square" style residence with hip roof; hip roof dormer with paired straight-headed windows with tracery in top light; first and second floor paired straight-headed windows; second floor porch with south bay glass paneled door; first floor full-width front porch with square Doric support, paneled rail and upper porch stick balustrade; south end entrance bay with glass paneled door flanked by elliptical leaded window.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
468	c.1896		Two-story, two-bay frame and shingle "Colonial Revival" style residence with hip roof with front projecting eave with dentils; three hip roof dormers with tripartite straight-headed one/one windows; two second floor semi-hexagonal bays with straight-headed windows; first floor full-width front porch with square Doric supports with separating curved arches and stick balustrade; south end entrance bay with glass paneled door flanked by small straight-headed window; first floor tripartite straight-headed one/one window; fluted Ionic building end pilasters. Contributing one-story frame garage, c. 1920.
472	c.1912		Two-story, two-bay frame residence with Colonial Revival styling with hip roof with projecting eaves; three hip roof dormers with paired six/one windows; second floor semi-hexagonal bay with straight-headed one/one windows with entablature surround; second floor porch with north bay multi-light double-sash door and stick balustrade; first floor full-width front porch with fluted Ionic columns and spindle balustrade; north entrance bay with glass and wood paneled door with sidelights; first floor tripartite single-light window with leaded transom. Contributing one-story frame garage, c. 1912.
476	c.1914		Two-story, two-bay shingle "American Four Square" style residence with hip roof with projecting eaves; three hip roof dormers with projecting eaves and four straight-headed one/one windows; two second floor semi-hexagonal bays with straight-headed double-hung windows; first floor full-width front porch with tapered square Doric supports, extending eave and shingled rail; south entrance bay with multi-light door flanked by straight-headed window; first floor tripartite window with entablature surround. Non-contributing one-story frame garage.
480	c.1913		Two and one-half story, two-bay frame and shingle residence with pedimented gable roof with front projecting eave with knee braces and tripartite straight-headed window with shed roof; second floor semi-hexagonal bay with straight-headed windows with leaded transoms; second floor porch with south bay glass and wood paneled door; first floor full-width partially enclosed front porch with tripartite window with single light with leaded transom; recessed south bay entrance with Doric column at corner, frieze with triglyph decoration and glass paneled door with multi-light sidelights. Contributing one-story frame garage, c. 1913.

<u>Address</u>	<u>Date</u>	<u>Photo</u>	<u>Description</u>
<u>Woodward Avenue, northwest side</u>			
488	c.1921		Two and one-half story, three-bay frame residence with front-facing gable roof; tripartite straight-headed double-hung gable window; second floor porch with center bay multi-light double-sash doors and end bays with straight-headed one/one windows; first floor full-width front sun porch with pilaster strips flanking bays and horizontal band of four straight-headed single-light windows with three-light transom; residence sided. Non-contributing one-story frame garage, c. 1921.
492	c.1902		Two and one-half story, two-bay frame residence with Colonial Revival styling with pedimented gable roof with front projecting eave and tripartite gable window; second floor semi-hexagonal bay with straight-headed one/one windows with entablature surround; second floor porch with north bay multi-light door flanked by small double-hung window; first floor full-width flat top hip roof porch with enclosed sun porch, four straight-headed three/one windows flanked by brick piers, recessed entrance with corner brick pier and wood paneled door with ten-light sidelights.
494	c.1902		Two and one-half story, two-bay frame residence with Colonial Revival styling with pedimented gable roof with front projecting eave and tripartite gable window; second floor semi-hexagonal bay with straight-headed double-hung windows; second floor porch with south bay multi-light door flanked by small double-hung window; north side two-story pedimented gable bay; first floor full-width enclosed sun porch with brick piers flanking four single-light windows, recessed south entrance bay with brick pier support and wood paneled multi-light door with sidelights.